



CODE ENFORCEMENT BOARD HEARING AGENDA

APRIL 26, 2016 9:00 AM

CITY COMMISSION MEETING ROOM - CITY HALL 100 N ANDREWS AVENUE FT. LAUDERDALE, FL 33301

CODE ENFORCEMENT BOARD

Code of Ordinances: Sec. 11-3.

PURPOSE: Hear and decide cases in which violations are alleged of any provision of the Florida Building Code, Broward County Amendments and violations of the Code of Ordinances of the City of Fort Lauderdale when alleged together with a violation of the Florida Building Code._

Note: If any person decides to appeal any decision made with respect to any matter considered at this public meeting or hearing he/she will need a record of the proceedings and for such purpose, he/she may need to ensure that a verbatim record of the proceedings is made, which record includes the testimony and evidence upon which the appeal is to be based.

Board Members: • Chad Thilborger, Chair • Paul Dooley, Vice Chair • Joan Hinton

- Lakhi Mohnani Patrick McGee Joshua Miron (alternate) Robert Smith (alternate)
- Michael Madfis (alternate) Board Attorney: Bruce Jolly

TWO OR MORE FORT LAUDERDALE CITY COMMISSIONERS OR MEMBERS OF A CITY OF FORT LAUDERDALE ADVISORY BOARD MAY BE IN ATTENDANCE AT THIS MEETING.

HEARING SCHEDULED

ASE NO: CE09120460

CASE ADDR: 2240 NW 30 TER
OWNER: BANK OF AMERICA NA

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN CHANGED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS OR INSPECTIONS:

- 1. INTERIOR REMODELING WORK. NEW DRYWALL ON CEILING AND WALLS
- 2. REROOF BETWEEN 2005 AND 2006.
- 3. NEW CABINETS AND FIXTURES IN THE KITCHEN AND BATHROOM AREAS.
- 4. NEW ENTRANCE DOORS WITH REDESIGNED OPENINGS.
- 5. ALL THE WINDOWS WERE REPLACED.
- 6. THE PROPERTY WAS BOARDED-UP WITHOUT A CERTIFICATE.

FBC(2007) 105.4.11

THE MECHANICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. A CENTRAL A/C SYSTEM WAS INSTALLED WITH DUCT WORK AND ELECTRICAL HEATER. VENTILATION SYSTEM FOR KITCHEN AND BATHROOMS.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

- 1. THE KITCHEN AND BATHROOM FIXTURES WERE REPLACED.
- 2. NEW SHOWER AND TUB WERE REPLACED.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. ELECTRICAL LOAD DEMAND WAS INCREASED BY ADDING A CENTRAL A/C WITH ELECTRICAL HEATERS AND ADDITIONAL LIGHTS, WALL OUTLETS THAT HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED AMPERAGE LOADING THROUGH THE PERMITTING PROCESS.

FBC(2007) 109.10

WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS THROUGH THE PERMITTING AND INSPECTION PROCESS.

FBC(2007) 1612.1.2

ALL THE WINDOWS AND DOOR INSTALLATIONS HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WIND LOADING THROUGH THE PERMITTING PROCESS.

FBC(2007) 1626.1

THE NEW WINDOWS AND DOOR WITH GLASS NEED TO BE IMPACT RESISTANT OR BE PROTECTED BY AN APPROVED HURRICANE PROTECTION SYSTEM.

CASE NO: CE14121358
CASE ADDR: 111 FLORIDA AVE
OWNER: AGUERO, VANESSA
INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. NEW KITCHEN CABINETS, AND EXTERIOR DOORS.
AS OF 12/02/2015 PERMITS HAVE NOT BEEN CLOSED,
INSPECTIONS NOT CALLED IN.

FBC(2010) 105.4.4

THE FOLLOWING WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

1. FIXTURES BEING CHANGED.

FBC(2010) 105.4.5

THE FOLLOWING WORK REQUIRES AN ELECRICAL PERMIT AND INSPECTIONS:

1. SWITCHES AND OUTLETS BEING CHANGED.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE15010467
CASE ADDR: 1951 NE 51 ST
OWNER: RODELU LLC
INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.4.11

THIS PROPERTY HAS BEEN ALTERED WITH THE

INSTALLATION OF AIR CONDITIONING UNITS WITHOUT THE

REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.5

THIS PROPERTY HAS BEEN ALTERED WITH THE

INSTALLATION OF ELECTRICAL WIRING AND DEVICES TO POWER AIR CONDITIONING UNITS WITHOUT THE REQUIRED

PERMITS AND/OR INSPECTIONS.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE15092363
CASE ADDR: 104 SE 11 AVE
OWNER: PIKUTA, MARIA
INSPECTOR: JOSE ABIN

VIOLATIONS: 9-279.(a)

PRESENT OCCUPANCY DOES NOT MEET THE SECTIONS OF

THIS CODE:

1. THERE ARE RENTAL UNITS THAT DO NOT HAVE SANITARY FACILITIES.

- 2. THERE ARE NO KITCHEN TYPE SINKS IN ANY UNIT AS REQUIRED.
- 3. RESIDENTS OF DIFFERENT GENDER SHARING COMMON BATHROOM FACILITIES.
- 4. ACCESS TO THE COMMON BATHROOM FACILITIES ONLY ACCESSIBLE FROM THE EXTERIOR OF THE DWELLING AND BUILDING.
- 5. THERE ARE NO 2 STOVE TYPE BURNERS IN ANY DWELLING UNIT AS REQUIRED.

FBC(2014) 1003.3.1

WINDOW A/C PROTRUDING INTO THE EGRESS PATH BELOW THE REQUIRED MINIMUM CAUSING A HAZARD.

FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. CONVERSION OF 3 APARTMENTS TO ROOMING HOUSE BY OBSTRUCTING DOORS.
- 2. BUILT COMMON BATHROOM OUT OF STORAGE CLOSET.
- 3. REMOVED KITCHENS AND CONVERTED TO ROOMS.
- 4. BUILT WALL TO CONVERT DINING ROOM TO A BOARDING ROOM.
- 5. MODIFIED WINDOW UNITS TO ACCOMODATE WINDOW AIR CONDITIONERS.

FBC (2014) 105.3.1.4.4

ALTERING, REPAIRING, INSTALLATION OF PLUMBING COMPONENTS AND/OR MODIFYING THE PLUMBING SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS. INSTALLATION AND MODIFICATION NOT LIMITED TO:

1. STORAGE CLOSET CONVERTED TO A BATHROOM WITH INSTALLATION OF PLUMBING FIXTURES AND MODIFICATIONS TO THE PLUMBING SYSTEM.

FBC(2014) 105.3.1.4.5

ALTERING, REPAIRING, INSTALLATION OF ELECTRICAL COMPONENTS AND/OR MODIFYING THE ELECTRICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS BUT NOT LIMITED TO:

1. INSTALLATION OF ELECTRICAL FIXTURES AND MODIFICATION OF THE ELECTRICAL SYSTEM BY INSTALLING OUTDOOR OUTLETS AND ELECTRICAL IN CLOSET CONVERTED TO BATHROOM.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

FBC (2014) 111.1.1

THE USE AND THE OCCUPANCY OF THIS DWELLING HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION OF A DUPLEX TO A FOURPLEX WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT.

CHANGED APPROVED USE OF 4 UNITS:

- 1. ADDED BOARDING ROOMS BY BUILDING WALL OBSTRUCTING DOORS AND NOW THERE ARE 4 RENTAL UNITS.
- 2. 3 DOWNSTAIRS APARTMENTS HAVE BEEN SUBDIVIDED BY BLOCKING DOORS AND ARE NOT ACCESSIBLE TO ALL THE RESIDENTS OF EACH APARTMENT.

NEC 110.26

ELECTRICAL BREAKER PANELS MUST BE ACCESSIBLE TO ALL RESIDENTS OF A DWELLING UNIT IN THE EVENT OF AN EMERGENCY WHERE POWER TO A CIRCUIT MUST BE DISCONNECTED.

CASE NO: CE15092413 CASE ADDR: 1536 NW 5 AV

OWNER: MERCADO, REINALDO J PEREZ H/E

KARAMANOGLOU, ALEX

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. EXTENSIVE REMODELING AND ALTERATIONS WITHOUT OBTAINING THE REQUIRED PERMITS MAY BE CITED IF DISCOVERED DURING THE CONSTRUCTION PROCESS. THIS INCLUDES STRUCTURAL ALTERATIONS MADE TO THE ROOF AND WALL STRUCTURE OF THE BUILDING.

FBC(2014) 105.3.1.4.10

THE FOLLOWING WORK REQUIRES A ROOF PERMIT AND INSPECTIONS:

1. RE-ROOFED THE STRUCTURE PRIOR TO OBTAINING THE REQUIRED PERMITS.

FBC(2014) 105.3.1.4.11

THE FOLLOWING WORK REQUIRES A MECHANICAL PERMIT AND INSPECTIONS:

1. THE REPLACEMENT OF THE EVAPORATOR UNIT, THERMOSTAT, THE CONDENSER UNIT, ALL REGISTERS AND ELECTRICAL CIRCUITS.

FBC(2014) 105.3.1.4.3

THE FOLLOWING WORK REQUIRES A DEMOLITION PERMIT AND INSPECTIONS:

1. COMPLETE INTERIOR DEMOLITION HAS BEEN PERFORMED PRIOR TO OBTAINING THE REQUIRED PERMITS.

FBC(2014) 105.3.1.4.4

THE FOLLOWING WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

1. PLUMBING ALTERATIONS, MODIFICATIONS, HAVE COMMENCED PRIOR TO OBTAINING THE REQUIRED PERMITS. THIS INCLUDES FIXTURES, SUPPLY LINES, WASTE DISPOSAL, IRRIGATION AND R & R SINKS/WATER BASINS.

FBC(2014) 105.3.1.4.5

THE FOLLOWING WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

1. THE INSTALLATION OF NEW ELECTRICAL PANEL, LIGHT FIXTURES, RE-WIRING, WALL OUTLETS, SWITCHES, A/C SUPPLY AND METER BASE.

FBC(2014) 107.1.1

SUBMITTAL OF 2 SETS OF PLANS AND SPECIFICATIONS AS OUTLINED IN THIS SECTION OF THE FLORIDA BUILDING CODE.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

FBC(2014) 115.1

DUE TO THE ONGOING NATURE OF THE WORK WITHOUT PERMITS A STOP WORK ORDER HAS BEEN ISSUED AND ANY FURTHER WORK AND ALTERATIONS MAY BE SUBJECT TO THE MAXIMUM PENALTIES OF \$500 PER DAY FOR VIOLATIONS OF THIS SECTION OF THE FLORIDA BUILDING CODE.

FBC(2014) 116.2.1.3.1

THIS BUILDING IN ITS PRESENT CONDITION DOES NOT MEET THE CRITERIA OF THE FLORIDA BUILDING CODE FOR MINIMUM MAINTENANCE STANDARD AND THE FORT LAUDERDALE MINIMUM HOUSING CODE. IT MUST BE REPAIRED BY THE OWNERS OR DEMOLISHED. WORK WITHOUT PERMITS DEEMED THIS BUILDING AS UNSAFE AND SUBJECT TO BOARD-UP AND/OR DEMOLITION UNDER THE SECTION OF THIS CODE.

CASE NO: CE15121156
CASE ADDR: 1115 NE 6 AV
OWNER: JONES, GLORIA M
INSPECTOR: JOSE ABIN

INDIEGION: CODE INTIN

VIOLATIONS: FBC(2010) 111.1.1

THIS DWELLING HAS BEEN DAMAGED BY FIRE. FIRE RESTORATION HAS BEEN DONE WITHOUT PERMITS. CERTIFICATES FOR OCCUPANCY DEEMING THE STRUCTURE SAFE AFTER FIRE DAMAGE HAVE NOT BEEN ISSUED.

FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. FIRE RESTORATION.
- 2. STORM SHUTTER INSTALLATION.
- 3. REPAIRING OF SMOKE AND FIRE DAMAGED INTERIOR WALLS.
- 4. BUILT SHEDS WHICH ARE NOW IN THE SETBACK.
- 5. PERMITS WERE ALLOWED TO EXPIRE AND WORK IS NOW WORK WITHOUT PERMIT.

FBC(2014) 105.3.1.4.11

THE MECHANICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED OR CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

- 1. REPLACED FIRE DAMAGED DUCT WORK.
- 2. NEW SPLIT SYSTEM EQUIPENT REPLACED.
- 3. PERMIT EXPIRED BECOMING WORK WITHOUT PERMIT.

FBC(2014) 105.3.1.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. REPLACEMENT OF PLUMBING FIXTURES.
- 2. PERMIT EXPIRED AND IT IS NOW WORK WITHOUT PERMITS.

FBC(2014) 105.3.1.4.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. ELECTRICAL REPAIRS DUE TO FIRE DAMAGE.
- 2. PERMIT EXPIRED AND IT IS NOW WORK WITHOUT PERMIT.

FBC(2014) 105.3.2.1

THE FOLLOWING PERMITS WERE LEFT TO EXPIRE: 99070788 Expired BSHUTTERST 1115 NE 06 AVJONES, GLORIA M STORM SHUTTERS 11120763 Expired BALTR1M 1115 NE 6 AV JONES, GLORIA M SFR REPLACE SMOKE DAMAGED DRYWALL 1000 SO FT 11120767 Expired MDUCT 1115 NE 6 AV JONES, GLORIA M REPLACE DUCTS BP 11120763 JONES, GLORIA M ELECTRIC FOR REPAIR SMOKE DAMAGE BP 11120763 Expired BALTR1M 1115 NE 6 AV JONES, GLORIA M SFR REPLACE SMOKE DAMAGED DRYWALL 1000 SQ FT 11120771 Expired PFIXREPLAC 1115 NE 6 AV JONES, GLORIA M REPLACE FIXTURES BP 11120763 JONES, GLORIA M ATF ELECTRICAL AS PER PLAN BP14120081 14120081 Expired BALTR1M 1115 NE 6 AV JONES, GLORIA M ATF REPAIR FIRE DAMAGE 14120101 Expired PFIXREPLAC 1115 NE 6 AV JONES, GLORIA M ATF REPLACE FIXTURES BP14120081

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

FBC(2014) 116.1.1

THIS BUILDING IN ITS PRESENT CONDITION DOES NOT MEET THE CRITERIA OF THE FLORIDA BUILDING CODE FOR MINIMUM MAINTENANCE STANDARD AND THE FORT LAUDERDALE MINIMUM HOUSING CODE. IT MUST BE

REPAIRED BY THE OWNERS AND INSPECTED.
WORK COMMENCED AND/OR COMPLETED PRIOR TO OBTAINING
THE REQUIRED PERMITS IS DEEMED AS UNSAFE UNDER
THIS SECTION OF THE FLORIDA BUILDING CODE.

CASE NO: CE15122129 CASE ADDR: 2810 NE 56 CT

OWNER: RINAUDO, FRANK J JR

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO: 1. REBUILDING OF DOCK.

FBC (2014) 105.3.1.4.4

THE FOLLOWING WORK REQUIRES A PLUMBING PERMIT:

1. INSTALLATION OF SOLAR PANELS ON ROOF.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE16010689
CASE ADDR: 1135 NW 7 AV

OWNER: TIITF/HRS-YOUTH SERV

BROWARD CHILDRENS SHELTER

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 111.1.1

THIS BUILDING WAS JOINED WITH A COMMON ROOF BREEZEWAY WITH 2 ADJACENT BUILDINGS WITH DIFFERENT

PROPERTY FOLIO NUMBERS. THE APPROVED USE OF THIS BUILDING IS FOR HALFWAY HOUSE PER PERMIT 90006599 AND THE USE IS THAT OF AN ADMINISTRATIVE BUILDING

WITH OFFICES, STORAGE AND KITCHEN.

FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. BUILT BREEZEWAY TO JOIN ADJACENT BUILDINGS ON PROPERTIES IDENTIFIED WITH DIFFERENT FOLIO NUMBERS. IN ADDTION THE INTERIOR FLOOR PLAN CONFIGURATION HAS BEEN CHANGED TO OFFICES, STORAGE AND A KITCHEN.

FBC(2014) 105.3.1.4.10

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. CONSTRUCTED ROOF BREEZEWAY WITH BUILDINGS ON ADJACENT PARCELS.

FBC(2014) 105.3.1.5

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS. SUBMIT "AS BUILT" ARCHITECTURAL DRAWINGS AND THE SCOPE OF WORK COVERING ALL EXISTING STRUCTURES AND MODIFICATIONS BUT NOT LIMITED TO:

1. ALL WALL STRUCTURES, ROOF STRUCTURES, ELECTRICAL SYSTEM, PLUMBING SYSTEM AND MECHANICAL SYSTEMS.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16010691 CASE ADDR: 1133 NW 7 AV

OWNER: TIITF/HRS-YOUTH SERV

BROWARD CHILDRENS SHELTER

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 111.1.1

THE USE AND THE OCCUPANCY OF THIS DWELLING HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION OF DUPLEX TO HALFWAY HOUSE WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT. COMMON ROOF HAS ENJOINED THE BUILDING ON THIS PARCEL WITH BUILDING ON ADJACENT PARCEL.

FBC (2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. CHANGED THE FLOORPLAN CONFIGURATION OF THE APPROVED USE AS A DUPLEX INTO A HALFWAY HOUSE WITH MULTIPLE SLEEPING ROOMS.

FBC(2014) 105.3.1.4.11

THE MECHANICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED OR CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. CHANGED THE CONFIGURATION OF THE MECHANICAL SYSTEM FROM THAT OF A DUPLEX TO A HALFWAY HOUSE WITH MULTIPLE SLEEPING QUARTERS.

FBC (2014) 105.3.1.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. CHANGED THE CONFIGURATION OF THE PLUMBING SYSTEM FROM THAT OF A DUPLEX TO A HALFWAY HOUSE WITH MULTIPLE SLEEPING OUARTERS.

FBC(2014) 105.3.1.4.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. CHANGED THE CONFIGURATION OF THE ELECTRICAL SYSTEM FROM THAT OF A DUPLEX TO A HALFWAY HOUSE WITH MULTIPLE SLEEPING OUARTERS.

FBC (2014) 105.3.1.5

SUBMIT "AS BUILT" ARCHITECTURAL DRAWINGS AND THE SCOPE OF WORK COVERING ALL EXISTING STRUCTURES AND MODIFICATIONS.

ALL WALL STRUCTURES, ROOF STRUCTURES, ELECTRICAL SYSTEM, PLUMBING SYSTEM AND MECHANICAL SYSTEMS.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16010692 CASE ADDR: 1141 NW 7 AV

OWNER: TIITF/HRS-YOUTH SERV

BROWARD CHILDRENS SHELTER

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 111.1.1

THE USE AND THE OCCUPANCY OF THIS DWELLING HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION OF DUPLEX TO HALFWAY HOUSE WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT. COMMON ROOF HAS ENJOINED THE BUILDING ON THIS PARCEL WITH BUILDING ON ADJACENT PARCEL.

FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. CHANGED THE FLOORPLAN CONFIGURATION OF THE APPROVED USE AS A DUPLEX INTO A HALFWAY HOUSE WITH MULTIPLE SLEEPING ROOMS.

FBC(2014) 105.3.1.4.11

THE MECHANICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED OR CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. CHANGED THE CONFIGURATION OF THE MECHANICAL SYSTEM FROM THAT OF A DUPLEX TO A HALFWAY HOUSE WITH MULTIPLE SLEEPING QUARTERS.

FBC(2014) 105.3.1.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. CHANGED THE CONFIGURATION OF THE PLUMBING SYSTEM FROM THAT OF A DUPLEX TO A HALFWAY HOUSE WITH MULTIPLE SLEEPING QUARTERS.

FBC(2014) 105.3.1.4.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. CHANGED THE CONFIGURATION OF THE ELECTRICAL SYSTEM FROM THAT OF A DUPLEX TO A HALFWAY HOUSE WITH MULTIPLE SLEEPING QUARTERS.

FBC(2014) 105.3.1.5

SUBMIT "AS BUILT" ARCHITECTURAL DRAWINGS AND THE SCOPE OF WORK COVERING ALL EXISTING STRUCTURES AND MODIFICATIONS.

1. ALL WALL STRUCTURES, ROOF STRUCTURES, ELECTRICAL SYSTEM, PLUMBING SYSTEM AND MECHANICAL SYSTEMS.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16010922
CASE ADDR: 621 SE 5 CT
OWNER: BLUEWATER INC
INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. THE INTERIOR OF THE STRUCTURE HAS BEEN GUTTED AND REMODELED.

FBC(2014) 105.3.1.4.11

THE MECHANICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED OR CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

- 1. CENTRAL A/C EQUIPEMENT.
- 2. DUCT WORK.
- 3. EXHAUST SYSTEMS.

FBC(2014) 105.3.1.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. BATHROOM AND KITCHEN FIXTURES.
- 2. LAWN IRRIGATION SYSTEM.
- 3. REBUILT THE PLUMBING SYSTEM TO SERVICE THE NEW INTERIOR REMODELING.

FBC(2014) 105.3.1.4.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. CIRCUIT BREAKER PANEL.
- 2. LIGHTING FIXTURES, OUTLETS AND FIXTURES.
- 3. CIRCUITRY FOR MECHANICAL SYSTEM.

FBC(2014) 105.3.1.5

SUPPORTING DOCUMENTATION FROM A QUALIFIED DESIGN PROFESSIONAL DETAILING AS BUILT SKETCHING AND SCOPE OF WORK OF ALL CONSTRUCTION, ALTERATIONS AND IMPROVEMENTS.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE15121837 CASE ADDR: 828 NW 14 WY

OWNER: LAZCO HOLDING GROUP

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INTERIOR REMODELING.

- 2. REBUILT/MODIFIED THE STRUCTURE PORCH ROOF DECK.
- 3. STRUCTURAL REPAIRS ON THE ROOF RAFTERS OF DWELLING.
- 4. ALTERATIONS OF INTERIOR WALLS.

FBC(2014) 105.3.1.4.10

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. RE-ROOFED THE STRUCTURE.

FBC(2014) 105.3.1.4.18

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. FENCE REPAIRS.

FBC(2014) 105.3.1.4.3

THIS BUILDING HAS BEEN ALTERED AND DEMOLITION WORK HAS BEEN PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. BATHROOM DEMOLITION.
- 2. KITCHEN DEMOLITION.
- 3. ELECTRICAL DEMOLITION.
- 4. PLUMBING DEMOLITION.
- 5. CEILING AND WALL COVERINGS HAVE BEEN DEMOLISHED AND REMOVED.

FBC(2014) 105.3.1.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. THE PLUMBING SYSTEM IN THE KITCHEN AND BATHROOMS HAS BEEN ALTERED.

FBC(2014) 105.3.1.4.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. THE ELECTRICAL SYSTEM HAS BEEN ALTERED THROUGHOUT THE STRUCTURE.

FBC (2014) 105.3.1.5

SUBMIT DRAWINGS AND A SCOPE OF WORK COVERING STRUCTURAL MODIFICATIONS. THE STRUCTURAL ALTERATIONS AND MODIFICATIONS MADE PRIOR TO OBTAINING THE REQUIRED PERMITS MUST BE UNCOVERED FOR INSPECTIONS AND/OR CERTIFIED BY A LICENSED DESIGN PROFESSIONAL.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

FBC (2014) 115.1

A STOP WORK WAS ISSUED.

STOP WORK ORDER ISSUED SINCE WORK IS ONGOING WITHOUT THE REQUIRED PERMITS. VIOLATION OF STOP WORK ORDER IS SUBJECT TO THE MAXIMUM PENALTIES AS OUTLINED UNDER THIS SECTION OF THE FLORIDA BUILDING CODE.

FBC(2014) 116.2.1.3.1

THIS BUILDING IN ITS PRESENT CONDITION DOES NOT MEET THE CRITERIA OF THE FLORIDA BUILDING CODE FOR MINIMUM MAINTENANCE STANDARD AND THE FORT LAUDERDALE MINIMUM HOUSING CODE. IT MUST BE REPAIRED BY THE OWNERS OR DEMOLISHED:
WORK COMMENCED AND/OR COMPLETED PRIOR TO OBTAINING THE REQUIRED PERMITS IS DEEMED AS UNSAFE AND SUBJECT TO HAVE THE STRUCTURE BOARDED UP AND/OR DEMOLISHED UNDER THIS SECTION OF THE FLORIDA BUILDING CODE.

THIS BUILDING IS DEEMED TO BE UNSAFE AND ELECTRICAL HAS BEEN DETERMINED TO BE A EXIGENT LIFE AND SAFETY HAZARD AND ENERGIZED CONNECTION TO THE POWER SUPPLY DISCONNECTED UNTIL A LICENSED ELECTRICIAN DEEMS IT TO BE SAFE.

CASE NO: CE14120486
CASE ADDR: 1633 SW 9 AV
OWNER: BERRY, TIMOTHY &

FOSTER, ANDREW L

INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED

PERMITS AND INSPECTIONS.

1. A TED SHED HAS BEEN LOCATED ON THE SOUTH SIDE NEXT TO 1635 SW 9 AVE HOUSE.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE15050401 CASE ADDR: 1820 NE 17 WAY

OWNER: FLORIDA CONFERENCE ASSN OF

SEVENTH DAY ADVENTISTS

INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED

PERMITS AND INSPECTIONS.

1. THE STAIR RAILINGS WERE REPLACED

2. A METAL STRUCTURE WAS ERECTED, LAYING PAVERS, BOTH ON THE BACK PATIO.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE15050755

CASE ADDR: 1200 NW 9 ST

OWNER: ASSIS HOMES LLC

INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. SINGLE FAMILY RESIDENCE CONVERTED INTO A

DUPLEX.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE15081715
CASE ADDR: 1533 NW 2 AV
OWNER: STOKES ONE LLC
INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. KITCHEN AND BATHROOMS REMODELED.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE15122078
CASE ADDR: 2360 NW 20 ST

OWNER: REYNOLDS, JOENATHAN C

INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

- 1. EXTERIOR DOORS REPLACEMENT.
- 2. KITCHENS AND BATHROOMS REMODELED.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE15122079
CASE ADDR: 2374 NW 20 ST

OWNER: REYNOLDS, JOENATHAN C

INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. EXTERIOR DOORS REPLACEMENT.

2. KITCHEN AND BATHROOMS REMODELLED.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE15111287

CASE ADDR: 2608 CASTILLA ISLE OWNER: ALLARD, ROBERT E INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO:

1. THE INSTALLATION OF A BOAT LIFT WITHOUT THE

REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE

IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15120123 CASE ADDR: 5870 NE 22 AV

OWNER: KONISKI, ANTOINE ALAZEMI, FAHED A M D

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED

PERMIT AND INSPECTIONS AS:

1. THE WINDOWS WERE REPLACED IN ALL THE OPENINGS.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE15120410 CASE ADDR: 824 NE 20 AV

OWNER: HG MIDDLE RIVER INVESTMENTS LLC

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO:

1. ALTERATIONS MADE SUCH AS RENOVATIONS, PAVERS AND FENCE INSTALLED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.11

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. MECHANICAL ALTERATIONS AND MINI SPLIT A/C SYSTEMS INSTALLED WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL ALTERATIONS MADE WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN

ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15121705
CASE ADDR: 630 NE 17 WY
OWNER: CESPEDES, EDWARD

FOLKER, MONIKA M

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ALTERATIONS MADE SUCH AS FRAMING, DRYWALL, WINDOWS AND DOORS ALTERED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. PLUMBING ALTERATIONS MADE WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

- 1. ELECTRICAL ALTERATIONS MADE WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.
- 2. THERE IS ALSO AN ELECTRICAL PANEL IN THE KITCHEN THAT WAS COVERED WITH A CABINET AND IS NOT PROPERLY SERVICEABLE.

FBC (2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

FBC(2014) 109.3.3

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY.

FBC(2014) 110.6

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16011814

CASE ADDR: 209 N FTL BEACH BLVD OWNER: THE SEASONS CONDO ASSN

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC (2014) 105.1

THIS CONDO BUILDING HAS BEEN ALTERED WITH REPAIRS BEING MADE TO THE PLUMBING DRAIN WASTE AND VENT STACK PIPES. IN THE COURSE OF DOING THESE PLUMBING REPAIRS THE FIREWALL IS BEING COMPROMISED AND IS NOT BEING PROPERLY REPAIRED BACK TO ITS ORIGINAL DESIGN FOR SUCH FIREWALL. THIS WORK IS BEING DONE WITHOUT THE REQUIRED STRUCTURAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS CONDO BUILDING IS BEING ALTERED WITH REPAIRS BEING MADE WHERE SECTIONS OF THE PLUMBING DRAIN WASTE AND VENT STACK PIPES ARE BEING REMOVED AND REPLACED WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS. THIS WORK IS BEING DONE IN BETWEEN THE PARTY WALLS AND IS CONSIDERED THE COMMON AREA OF THE BUILDING AND THE CONDO BUILDINGS RESPONSIBILITY.

FBC (2014) 109.3.3

THE CONDO BUILDING WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY.

FBC(2014) 110.6

THE CONDO BUILDING WILL NEED TO SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16021379 CASE ADDR: 2149 NE 56 PL

OWNER: GOLDSZLAGER, HERMAN

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

- 1. ALTERATIONS MADE SUCH AS KITCHEN AND BATHROOM REMODELING.
- 2. WINDOWS REPLACED.
- 3. DRIVEWAY REDONE WITH AN ASPHALT TOPPING.
 THIS WORK WAS PERFORMED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. PLUMBING FIXTURES REMOVED AND REPLACED IN THE KITCHEN AND BATHROOMS WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL REMOVED AND REPLACED IN THE KITCHEN AND BATHROOMS WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16030328 CASE ADDR: 625 NE 14 AVE

OWNER: MULTICREDITO INTERNATIONAL LLC

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ALTERATIONS MADE SUCH AS FRAMING, DRYWALL, WINDOWS AND DOORS WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.11

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. MECHANICAL ALTERATIONS MADE INCLUDING ADDING MINI SPLIT A/C UNITS WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. PLUMBING ALTERATIONS MADE INCLUDING REMOVING AND REPLACING PLUMBING FIXTURES AND ADDING TANKLESS WATER HEATERS WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL ALTERATIONS MADE INCLUDING REMOVING AND REPLACING ELECTRICAL DEVICES AND ELECTRICAL PANELS WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

FBC(2014) 109.3.3

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY.

FBC(2014) 110.6

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16030521

CASE ADDR: 5100 DUPONT BLVD # 2A
OWNER: MORRISON, JUDITH P
INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC (2014) 105.1

THIS CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ALTERATIONS MADE SUCH AS FRAMING AND DRYWALL WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

- 1. ELECTRICAL ALTERATIONS MADE, THE ELECTRICAL PANEL UPGRADED AND RELOCATED.
- 2. HI-HAT LIGHT FIXTURES INSTALLED.
- 3. DEVICES REMOVED, REPLACED AND RELOCATED WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

FBC(2014) 109.3.3

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY.

FBC(2014) 110.6

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

RETURN HEARING (OLD BUSINESS)

CASE NO: CE13031281

CASE ADDR: 2609 E LAS OLAS BLVD OWNER: BRANDT-ALBERT, MARIA M

MARIA M BRANDT-ALBERT REV TR

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

- 1. THIS PROPERTY HAS BEEN ALTERED WITH AN ADDITION BUILT ON THE EAST SIDE OF THE HOUSE WITHOUT THE REOUIRED PERMITS AND/OR INSPECTIONS.
- 2. THIS PROPERTY HAS BEEN ALTERED WITH THE INSTALLATION OF A CARPORT/AWING STRUCTURE WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.
- 3. THIS PROPERTY HAS BEEN ALTERED WITH A DOCK STRUCTURE BUILT WITHOUT A PERMIT RECORD OR INSPECTION RECORD FOR THIS BOAT DOCK.

FBC(2010) 105.4.1

THIS PROPERTY HAS BEEN ALTERED WITH A PATIO ROOF STRUCTURE INSTALLED ON THE N.W. CORNER OF THE PROPERTY WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.5

THIS PROPERTY HAS BEEN ALTERED WITH ELECTRICAL WORK INSTALLED ON THE DOCK AND OTHER AREAS OF UNPERMITTED (ADDITIONS) WORK WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.8

THIS PROPERTY HAS BEEN ALTERED WITH AN AWNING INSTALLED ON THE WEST SIDE OF THE HOUSE WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 110.9

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS AND PASS THE AFTER THE FACT PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE13080252

CASE ADDR: 2500 E COMMERCIAL BLVD

OWNER: ALTO PROPERTY MANAGEMENT LLC

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. INTERIOR RENOVATIONS.

FBC(2010) 110.9

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

FBC(2010) 105.4.4

THIS COMMERCIAL SPACE HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. PLUMBING FIXTURES INSTALLED WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2010) 105.4.5

THIS COMMERCIAL SPACE HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL WIRING AND DEVICES INSTALLED WITHOUT THE REQUIRED ELECTRICAL PERMITS AND/OR INSPECTIONS.

FBC (2010) 105.4.11

THIS COMMERCIAL SPACE HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE MECHANICAL SYSTEM IS BEING ALTERED WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

CASE NO: CE15102509

CASE ADDR: 2500 E COMMERCIAL BLVD

OWNER: ALTO PROPERTY MANAGEMENT LLC

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THIS COMMERCIAL OFFICE SPACE AND THE ADJOINING UNITS, PROFESSIONAL DRAWINGS PREPARED BY A DESIGN PROFESSIONAL WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED AND BROUGHT INTO COMPLIANCE PER FLORIDA BUILDING CODE.

FBC(2014) 109.3.3

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY.

FBC(2014) 110.6

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

FBC(2014) 105.1

THIS COMMERCIAL SPACE HAS BEEN COMPLETELY REMODELED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. FRAMING AND DRYWALL INSTALLED WITHOUT THE REQUIRED STRUCTURAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS COMMERCIAL SPACE HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. PLUMBING FIXTURES INSTALLED WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS COMMERCIAL SPACE HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL WIRING AND DEVICES INSTALLED WITHOUT THE REQUIRED ELECTRICAL PERMITS AND/OR INSPECTIONS.

CASE NO: CE15091410

CASE ADDR: 736 N VICTORIA PARK RD OWNER: MARTINON, MARIE LAURENCE

TERNINCK, JANINE

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WITH WORK PERFORMED WHICH INCLUDES BUT IS NOT LIMITED TO:

- 1. DRIVEWAY HAS BEEN DEMOLISHED.
- 2. A CONCRETE PATIO AND WALKWAY HAVE BEEN POURED AT THE FRONT OF THE HOUSE.
- 3. WINDOWS WERE REPLACED.
- 4. THE KITCHEN AND INTERIOR WERE REMODELED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS PROPERTY HAS BEEN ALTERED WITH PLUMBING WORK PERFORMED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE REMOVAL AND REPLACEMENT OF PLUMBING FIXTURES IN THE KITCHEN WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY HAS BEEN ALTERED WITH ELECTRICAL WORK PERFORMED WHICH INCLUDES BUT IS NOT LIMITED TO: THE ELECTRICAL PANEL BEING REPLACED, THE KITCHEN BEING REMODELED TO INCLUDE REPLACING DEVICES AND OTHER INTERIOR ELECTRICAL WORK WITHOUT THE REQUIRED PERMITS AND OR INSPECTIONS.

FBC(2014) 109.3.3

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY.

FBC(2014) 110.6

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE13091177 CASE ADDR: 3210 NW 63 ST

OWNER: STYCZYNSKY, RANDALL W

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

1. REPLACING WINDOWS AND DOORS.

2. ALTERING OPENING FROM WINDOWS TO DOORS, WHICH INCLUDES FILLED CELLS AND ELECTRICAL WORK.

ALL WORK DONE WITHOUT THE REQUIRED PERMITS OR INSPECTIONS.

FBC (2010) 105.4.15

REPLACING WINDOWS AND DOORS WITHOUT THE REQUIRED PERMIT OR INSPECTIONS.

FBC(2010) 105.4.5

ADDING ELECTRICAL WIRING, ELECTRICAL BOXES, AND FUTURE FIXTURES WITHOUT THE REQUIRED PERMIT OR INSPECTIONS.

FBC(2010) 1604.1

ALTERING EXTERIOR OPENINGS FOR BOTH WINDOWS AND DOORS THAT INCLUDES FILLED CELLS, BLOCK, POURED SILLS WITHOUT THE REQUIRED PERMIT OR INSPECTIONS.

CASE NO: CE14010955

CASE ADDR: 200 S BIRCH RD # 1110

OWNER: KILCOYNE, JOE INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES

BUT IS NOT LIMITED TO:

1. THE RENOVATION OF THE KITCHEN AND BATHROOM WITHOUT THE REQUIRED STRUCTURAL PERMIT AND/OR INSPECTIONS.

FBC(2010) 105.4.4

THIS CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE RENOVATION OF THE KITCHEN AND BATHROOM WITH THE REMOVAL AND REPLACEMENT OF THE PLUMBING FIXTURES WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2010) 105.4.5

THIS CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO THE RENOVATION OF THE KITCHEN AND BATHROOM WHICH INCLUDES BUT IS NOT LIMITED TO:

- 1. REMOVING AND REPLACING ELECTRICAL DEVICES WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.
- 2. THE ELECTRICAL PANEL IN THIS UNIT HAS ALSO BEEN REPLACED WITHOUT PERMITS.

FBC(2010) 110.9

THE CONDO UNIT OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE14011724 CASE ADDR: 1245 NE 12 AV

OWNER: SAMAYOA, DOMINGO A & TELMA E

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 116.2.1.2.1

THE BUILDING AT THIS PROPERTY WAS HIT BY A CAR AND THE GARAGE HAS STRUCTURAL DAMAGE TO THE COLUMN AND TIE BEAM. THIS BUILDING REQUIRES STRUCTURAL REPAIRS.

FBC(2010) 116.2.1.2.3

THE BUILDING AT THIS PROPERTY WAS HIT BY A CAR AND THE GARAGE HAS STRUCTURAL DAMAGE TO THE COLUMN AND TIE BEAM. THIS BUILDING REQUIRES STRUCTURAL REPAIRS.

FBC(2010) 110.9

THE BUILDING AT THIS PROPERTY WAS HIT BY A CAR AND THE GARAGE HAS STRUCTURAL DAMAGE TO THE COLUMN AND TIE BEAM. THIS BUILDING REQUIRES STRUCTURAL REPAIRS.

CASE NO: CE14022168

CASE ADDR: 5100 BAYVIEW DR # 301 OWNER: BONELL, JOSEPHINE INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

INTERIOR REMODELING WORK DONE WITHOUT THE REQUIRED

PERMITS AND/OR INSPECTIONS.

CASE NO: CE14060058
CASE ADDR: 2500 LUCILLE DR
OWNER: KLAIRMONT, LARRY
INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THERE ARE SEVERAL ITEMS THAT HAVE BEEN INSTALLED ON THIS PROPERTY WITHOUT FIRST OBTAINING THE

REQUIRED PERMITS TO INCLUDE:

A SMALL SHED.
 A GENERATOR.
 AN AWNING.
 A POOL HEATER.

CASE NO: CE14110272

CASE ADDR: 1311 SEMINOLE DR
OWNER: DANIELSSON, LEIF
INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS PROPERTY IS BEING ALTERED WITH THE FOLLOWING WORK BEING DONE WITHOUT THE REQUIRED PERMITS

AND/OR INSPECTIONS. THIS WORK INCLUDES BUT IS NOT

LIMITED TO:

1. EXTERIOR WALL REPAIR.

NEW DOCK.
 NEW TIKI HUT.

4. WHAT APPEARS TO BE POST FOR A FENCE OR

TRELLIS.

5. REMOVING AND REPLACING A PAVER DECK.

CASE NO: CE14110327
CASE ADDR: 433 NE 14 AVE
OWNER: BROOKS, SCOTT

NEW OWNER: ALEXANDRA SANTIBANEZ IRREV TR

SANTIBANEZ, ONEY TRSTEE

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS PROPERTY HAS BEEN ALTERED WITH THE INTERIOR DEMOLITION AND REMODELING WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 110.9

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15011800

CASE ADDR: 229 S FTL BEACH BLVD OWNER: EL-AD FL BEACH CR LLC

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS PROPERTY HAS BEEN ALTERED WITH THE INSTALLATION OF AN AWNING DISPLAYING SIGNAGE WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.8

THIS PROPERTY HAS BEEN ALTERED WITH THE INSTALLATION OF AN ALUMINUM AWNING STRUCTURE WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 110.9

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15102548

CASE ADDR: 200 S BIRCH RD # 209

OWNER: FEDERAL NATIONAL MORTGAGE ASSN

INSPECTOR: ROBERT MASULA

VIOLATIONS: 9-280(B)

THERE ARE BUILDING PARTS WHICH ARE DETERIORATED AND NOT MAINTAINED.

- 1. THIS CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:
- A. THE ORIGINAL A/C WALL UNIT APPLIANCE HAS BEEN REMOVED ALONG WITH THE ORIGINAL APPLIANCE SHELVES THAT WAS ORIGINALLY ANCHORED INTO THE WALL OPENING. THE OPENINGS EITHER NEED TO BE PROPERLY CLOSED IN WITH A STRUCTURAL PERMIT SPECIFYING THE METHOD OF CONSTRUCTION TO BE USED. IF THE INTENTION IS TO REPLACE THESE A/C WALL APPLIANCE UNITS THEN A COMPLETE UNIT WITH THE STRUCTURAL ATTACHED SHELVES NEEDS TO BE PROPERLY INSTALLED AND ANCHORED INTO THE WALL OPENING. THIS WILL AT A MINIMUM REQUIRE A MECHANICAL PERMIT FOR REPLACING THE ENTIRE ASSEMBLY.

FBC(2014) 105.3.1.4.4

THIS CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE PLUMBING BEING ALTERED IN THE BATHROOM BY REMOVING AND REPLACING THE TOILET AND SINK WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTION.

FBC(2014) 105.3.1.4.5

THIS CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE ELECTRICAL PANEL BEING REMOVED AND REPLACED WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 110.6

THE CONDO UNIT OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15081042

CASE ADDR: 441 S FTL BEACH BLVD OWNER: SOPHIA ENTERPRISES INC

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2014) 105.1

THIS COMMERCIAL BUILDING SPACE HAS BEEN ALTERED WITH STRUCTURAL ALTERATIONS WHICH INCLUDE BUT ARE NOT LIMITED TO:

- 1. THE COMPLETE BUILD-OUT OF A RESTAURANT.
- 2. NEW WINDOWS AND DOORS.
- 3. INTERIOR ALTERATIONS WITHOUT THE REQUIRED STRUCTURAL PERMIT AND/OR INSPECTIONS.

FBC (2014) 105.3.1.4.11

THIS COMMERCIAL BUILDING SPACE HAS BEEN ALTERED WITH MECHANICAL ALTERATIONS WHICH INCLUDE BUT ARE NOT LIMITED TO:

1. NEW A/C MECHANICAL UNITS AND DUCT WORK INSTALLED WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS COMMERCIAL BUILDING SPACE HAS BEEN ALTERED WITH PLUMBING ALTERATIONS WHICH INCLUDE BUT ARE NOT LIMITED TO:

1. PLUMBING FIXTURES INSTALLED WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS COMMERCIAL BUILDING SPACE HAS BEEN ALTERED WITH ELECTRICAL ALTERATIONS WHICH INCLUDE BUT ARE NOT LIMITED TO:

- 1. ALARM CONTROL PANEL.
- 2. LIGHTING.
- 3. ELECTRICAL CONDUIT, ELECTRICAL DISCONNECTS, LOW VOLTAGE INSTALLED WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 107.1.1

THIS CODE CASE AND THE WORK DONE IN THIS
COMMERCIAL BUILDING SPACE WILL REQUIRE
ARCHITECTURAL DRAWINGS PREPARED BY A DESIGN
PROFESSIONAL TO INCLUDE ALL OF THE VIOLATIONS THAT
NEED TO BE PROPERLY PERMITTED, CORRECTED AND
INSPECTED AS REQUIRED BY THE FLORIDA BUILDING
CODE.

FBC(2014) 109.3.3

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15040668

CASE ADDR: 619 N FTL BEACH BLVD

OWNER: SEA CLUB OCEAN RESORT HOTEL INC

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC (2010) 105.1

THIS PROPERTY HAS BEEN ALTERED WITH THE

INSTALLATION OF A CONCRETE BLOCK WALL, WINDOWS, RAILING AND OTHER REMODELING WORK WITHOUT THE

REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 110.9

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE

IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15040732 CASE ADDR: 1032 NE 15 AVE

OWNER: YUTHASUNTHORN FAMILY ENTERPRISES IN

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS PROPERTY HAS BEEN ALTERED WITH EXTENSIVE INTERIOR AND EXTERIOR REMODELING WITHOUT THE REQUIRED STRUCTURAL PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.3

THIS PROPERTY HAS BEEN ALTERED WITH EXTENSIVE INTERIOR DEMOLITIONS WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.5

THIS PROPERTY HAS BEEN ALTERED WITH EXTENSIVE ELECTRICAL WORK BEING DONE INCLUDING REPLACING THE ELECTRICAL PANEL WITHOUT THE REOUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2010) 110.9

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE AFTER THE FACT PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CASE IS FULLY COMPLIED AND CLOSED.

CE15082281 CASE NO:

CASE ADDR: 2400 E OAKLAND PARK BLVD

SP4 INVESTMENTS LLC

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY/COMMERCIAL SPACE HAS BEEN ALTERED TO INCLUDE BUT IS NOT LIMITED TO:

1. A ROOM CONVERTED INTO A SHOWER.

2. A ROOM ALTERED INTO A KITCHENETTE WITH A WASHER AND DRYER. THIS WORK INCLUDES FRAMING AND DRYWALL WORK DONE WITHOUT THE REQUIRED PERMITS AND/OR

INSPECTIONS.

FBC(2014) 105.3.1.4.11

THIS PROPERTY/COMMERCIAL SPACE HAS BEEN ALTERED TO INCLUDE BUT IS NOT LIMITED TO:

1. MECHANICAL WORK INSTALLED FOR THE INSTALLATION OF A DRYER WITHOUT THE REQUIRED PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS PROPERTY/COMMERCIAL SPACE HAS BEEN ALTERED TO INCLUDE BUT IS NOT LIMITED TO:

1. PLUMBING WORK INSTALLED TO INCLUDE A NEW SHOWER, A WASHER MACHINE, AND A TANKLESS WATER HEATER INSTALLED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY/COMMERCIAL SPACE HAS BEEN ALTERED TO INCLUDE BUT IS NOT LIMITED TO:

1. ELECTRICAL WORK INSTALLED TO INCLUDE ELECTRICAL FOR A WASHER AND DRYER, ELECTRICAL SUB PANEL INSTALLED UNDER THE KITCHENETTE SINK FOR A TANKLESS WATER HEATER AND POSSIBLY OTHER APPLIANCES. THERE ARE MISCELLANEOUS ELECTRICAL REPAIRS OR ALTERATIONS THAT HAVE BEEN MADE WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 107.1.1

BECAUSE OF THE SEVERITY AND COMPLEXITY OF THIS CODE CASE AND THE ALTERATIONS THAT HAVE BEEN MADE TO THIS COMMERCIAL SPACE, THIS CASE WILL REQUIRE DRAWINGS PREPARED BY A DESIGN PROFESSIONAL. THESE DRAWINGS NEED TO DOCUMENT THE VIOLATIONS THAT EXIST AND THE METHOD AND CORRECTIONS THAT NEED TO BE MADE TO CORRECT ALL OF THE VIOLATIONS THAT EXIST IN THIS COMMERCIAL SPACE.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15101220 CASE ADDR: 1230 NW 7 AV

OWNER: GALA INVESTMENTS GROUP LLC

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

- 1. A COMPLETE INTERIOR REMODELING OF THE KITCHEN AND BATHROOM.
- 2. THERE IS A SECOND BATHROOM THAT WAS ILLEGALLY INSTALLED IN THIS HOUSE AND WAS NEVER PERMITTED. THIS WORK HAS BEEN PERFORMED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.11

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE MECHANICAL SYSTEM INCLUDING THE DUCT WORK BEING REMOVED AND REPLACED WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

- 1. THE PLUMBING BEING ALTERED IN THE KITCHEN AND BATHROOM.
- 2. A SECOND BATHROOM WAS ADDED WITHOUT THE REQUIRED PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

- 1. THE ELECTRICAL BEING ALTERED IN THE KITCHEN AND BATHROOM.
- 2. A SECOND BATHROOM ILLEGALLY ADDED WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

FBC(2014) 107.1.1

THIS PROPERTY AND CODE CASE WILL REQUIRE DRAWINGS PREPARED BY A DESIGN PROFESSIONAL TO ADDRESS AND PERMIT THE SECOND BATHROOM THAT WAS ILLEGALLY

INSTALLED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC (2014) 109.3.3

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY.

CASE NO: CE15102069

CASE ADDR: 1220 NE 3 ST # 103

OWNER: SWEENEY, THOMAS A & GLORIA &

SWEENEY, MICHAEL

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2014) 109.3.3

THE CONDO UNIT OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY.

FBC(2014) 105.1

THIS CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. AN INTERIOR REMODEL AND REMODELING OF THE BATHROOM WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE PLUMBING BEING ALTERED WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE ELECTRICAL BEING ALTERED WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC (2014) 110.6

THE CONDO UNIT OWNER WILL BE REQUIRED TO SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15051433 CASE ADDR: 1728 NE 20 AVE

OWNER: CARL A HOLCOMB REV LIV TR

HOLCOMB, CARL A TRSTEE

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. A/C UNITS WERE INSTALLED.
- 2. KITCHEN CABINETS ARE BEING REPLACED WHICH REQUIRE PLUMBING PERMIT FOR SINK INSTALLATION AND ELECTRICAL PERMIT FOR GFI ON THE COUNTER.

FBC(2010) 105.4.11

THE MECHANICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED OR CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO: 1. INSTALLATION OF DUCTLESS A/C UNITS.

FBC(2010) 105.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:
1. SINK INSTALLATION FOR KITCHEN CABINETS.

FBC(2010) 105.4.5

THE ELECTRICAL IN THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. ELECTRICAL GFI FOR KITCHEN CABINETS AND

ELECTRICAL FOR A/C UNITS.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITING PROCESS.

CASE NO: CE15061470
CASE ADDR: 1638 RIVER LN
OWNER: COMMISSO, HELEN

HELEN G MACALPINE REV TR

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC (2010) 105.1

THIS PROPERTY HAS BEEN ALTERED WITH EXTENSIVE INTERIOR AND EXTERIOR REMODELLING BEING DONE WITHOUT THE REQUIRED STRUCTURAL PERMITS AND/OR INSPECTIONS.

FBC(2010) 110.9

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

FBC(2010) 105.4.5

THIS PROPERTY HAS BEEN ALTERED WITH EXTENSIVE INTERIOR AND EXTERIOR REMODELLING BEING DONE WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2010) 105.4.4

THIS PROPERTY HAS BEEN ALTERED WITH EXTENSIVE REMODELLING WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2010) 105.4.11

THIS PROPERTY HAS BEEN ALTERED WITH EXTENSIVE REMODELLING BEING DONE WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

CASE NO: CE15110968

CASE ADDR: 3821 N OCEAN BLVD OWNER: MY FL 3821 LLC INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. INTERIOR ROOM REMODELING INCLUDING FRAMING, DRYWALL, INTERIOR WALL BOARD CLADDING, WOOD PLATFORM DECK INSTALLED WITHOUT THE REQUIRED STRUCTURAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL DEVICES BEING REMOVED AND REPLACED, ELECTRICAL WIRING BEING INSTALLED OR ALTERED TO ACCOMMODATE NEW ELECTRICAL FIXTURES AND LOW VOLTAGE LIGHTING INSTALLED WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

- 1. THE PLUMBING FIXTURES ARE BEING REMOVED AND REPLACED.
- 2. THERE ARE ROOMS WHERE A KITCHENETTE WAS REMOVED, A WOOD PLATFORM DECK BUILT AND JACUZZI TUBS INSTALLED. THIS WORK HAS BEEN PERFORMED WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2014) 107.1.1

BECAUSE OF THE SCOPE OF WORK, THE DOLLAR AMOUNT OF THE IMPROVEMENTS BEING MADE, THE POTENTIAL LIABILITY TO THIS HOTEL BUILDING AND OCCUPANTS, PROFESSIONAL DRAWINGS PREPARED BY A DESIGN PROFESSIONAL WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED AND BROUGHT INTO COMPLIANCE PER THE FLORIDA BUILDING CODE.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15120399 CASE ADDR: 2157 NE 63 CT

OWNER: ASURION FINANCIAL INC

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE KITCHEN AND BATHROOMS ARE BEING COMPLETELY DEMOLISHED AND REMODELED WHICH INCLUDES FRAMING AND DRYWALL WORK PERFORMED WITHOUT THE REQUIRED STRUCTURAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE KITCHEN AND BATHROOMS ARE BEING COMPLETELY DEMOLISHED AND REMODELED WHICH INCLUDES REMOVING AND REPLACING THE PLUMBING FIXTURES WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE KITCHEN AND BATHROOMS ARE BEING REMODELED WHICH INCLUDES REMOVING AND REPLACING ELECTRICAL DEVICES WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 109.3.3

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY.

FBC(2014) 110.6

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15120539

CASE ADDR: 3020 SEVILLE ST

OWNER: 3020 SEVILLE PROPERTIES LLC

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

- 1. WINDOWS AND DOORS BEING REPLACED.
- 2. REMODELING OF THE INTERIOR ROOMS WHICH INCLUDE FRAMING AND DRYWALL.
- 3. REBUILDING EXTERIOR STAIRS AND DECKS.
- 4. REPLACING THE ROOF ALONG WITH NEW A/C. ROOF STANDS WITHOUT THE REQUIRED STRUCTURAL PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE KITCHENETTES AND BATHROOMS ARE BEING COMPLETELY REMODELED. REMOVING AND REPLACING PLUMBING FIXTURES THROUGHOUT THE BUILDING WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL WORK IS BEING DONE THROUGHOUT THE BUILDING WHICH INCLUDES NEW WIRING, NEW LOW VOLTAGE WIRING, NEW ELECTRICAL BOXES, NEW ELECTRICAL DISCONNECTS AND ELECTRICAL DEVICES BEING REMOVED AND REPLACED WITHOUT THE REQUIRED ELECTRICAL PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.11

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. MECHANICAL WORK IS BEING PERFORMED WHICH INCLUDES INSTALLING NEW MINI SPLIT A/C SYSTEMS FOR THE ROOMS AND NEW UNITS PLACED ON THE GROUND AND ROOF WITHOUT THE REQUIRED MECHANICAL PERMITS AND/OR INSPECTIONS.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THESE HOTEL UNITS AND THE HOTEL BUILDING, PROFESSIONAL DRAWINGS PREPARED BY A DESIGN PROFESSIONAL WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

FBC(2014) 109.3.3

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY.

FBC (2014) 110.6

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15120540 CASE ADDR: 3024 SEVILLE ST

OWNER: 3020 SEVILLE PROPERTIES LLC

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

- 1. WINDOWS AND DOORS BEING REPLACED.
- 2. REMODELING OF THE INTERIOR ROOMS WHICH INCLUDE FRAMING AND DRYWALL, REBUILDING EXTERIOR STAIRS AND DECKS, AND REPLACING THE ROOF ALONG WITH NEW A/C. ROOF STANDS WITHOUT THE REQUIRED STRUCTURAL PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.11

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. MECHANICAL WORK BEING PERFORMED WHICH INCLUDES INSTALLING NEW MINI SPLIT A/C SYSTEMS FOR THE ROOMS AND NEW UNITS PLACED ON THE GROUND AND ROOF WITHOUT THE REQUIRED MECHANICAL PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE KITCHENETTES AND BATHROOMS ARE BEING

COMPLETELY REMODELED AND REMOVING AND REPLACING PLUMBING FIXTURES THROUGHOUT THE BUILDING WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL WORK BEING DONE THROUGHOUT THE BUILDING WHICH INCLUDES NEW WIRING, NEW LOW VOLTAGE WIRING, NEW ELECTRICAL BOXES, NEW ELECTRICAL DISCONNECTS AND ELECTRICAL DEVICES BEING REMOVED AND REPLACED WITHOUT THE REQUIRED ELECTRICAL PERMITS AND/OR INSPECTIONS.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THESE HOTEL UNITS AND THE HOTEL BUILDING, PROFESSIONAL DRAWINGS PREPARED BY A DESIGN PROFESSIONAL WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

FBC(2014) 109.3.3

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY.

FBC(2014) 110.6

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16011026
CASE ADDR: 1009 NE 17 CT
OWNER: CONROY, KYLE
INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ALTERATIONS MADE SUCH AS FRAMING AND DRYWALL WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS. THIS PROPERTY WAS ORIGINALLY PERMITTED AS A TWO FAMILY DWELLING AND WAS ILLEGALLY CONVERTED IN A TRIPLEX UNIT WITHOUT THE PROPERTY CERTIFICATE OF OCCUPANCY. THERE HAS BEEN EXTENSIVE REMODELING

WORK DONE ON THIS BUILDING WHICH INCLUDES BUT IS NOT LIMITED TO WINDOWS AND DOORS REPLACED, KITCHEN AND BATHROOM REMODELED, LAYOUT OF THE BUILDING HAS BEEN ALTERED.

FBC(2014) 105.3.1.4.4

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. PLUMBING ALTERATION MADE:
A. REMODELING KITCHENS, BATHROOMS, REMOVING AND REPLACING PLUMBING FIXTURES WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

- 1. ELECTRICAL ALTERATIONS MADE:
- A. ELECTRICAL PANELS REPLACED, DISCONNECTS INSTALLED, ELECTRICAL OUTLETS, SWITCHES, DEVICES REMOVED, REPLACED OR RELOCATED WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.11

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. MECHANICAL ALTERATIONS MADE WITH REMOVING AND REPLACING THE A/C UNITS WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY, PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

CASE NO: CE16030002

CASE ADDR: 2933 POINSETTIA ST

OWNER: CORTEZ PROPERTY DEV LLC

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2014) 105.3.1.4.18

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO:

1. A FENCE INSTALLED AROUND THE PERIMETER OF THIS PROPERTY WITHOUT THE REQUIRED PERMITS AND OR

INSPECTIONS.

FBC (2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE14051440 CASE ADDR: 1663 NW 15 TER OWNER: ALLADIN, VANEL INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS:

- 1. THE DWELLING'S OPENINGS WERE BOARDED AND THE WOOD HAS BEEN REMOVED.
- 2. NEW WINDOWS AND EXTERIOR DOORS WERE INSTALLED ON THEM.
- 3. INTERIOR UPGRADE INSIDE THE KITCHEN AND BATHROOMS AREAS.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE14061177 CASE ADDR: 3505 SW 12 CT

OWNER: MCFARLANE, CHRISTINE INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS, INSPECTIONS AND THE CERTIFICATE OF OCCUPANCY:

- 1. THE GARAGE OR CARPORT WAS ENCLOSED INTO LIVING SPACE WITHOUT A C.O.
- 2. THE WINDOWS IN THE DWELLINGS' OPENINGS WERE REPLACED.
- 3. THE KITCHEN AND BATHROOM WERE UPGRADED WITH NEW PLUMBING AND ELECTRICAL FIXTURES.
- 4. NEW CABINETRY WAS INSTALLED.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE15081007

CASE ADDR: 750 ALABAMA AVE

OWNER: HERMES PROPERTY DEVELOPMENT LLC

%TED KAY JR

INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. KITCHEN AND BATHROOM RENOVATION.
- 2. ADDITION OF A SECOND BATHROOM IN UTILITY ROOM AREA.
- 3. REPLACEMENT OF FRONT DOOR AND WINDOWS.
- 4. ALTERATION OF ELECTRICAL SYSTEM IN UTILITY ROOM.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT, THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE14090643

CASE ADDR: 6311 BAY CLUB DR # 6311-3 OWNER: PIERCE, JOSEPH & JANET

INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC (2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO: 1. KITCHEN REMODELING.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE15011568
CASE ADDR: 1348 SW 30 ST

OWNER: HOLLAND, ANDREW & TABITHA

INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. WOODEN GATES INSTALLATION.

CASE NO: CE15051584

CASE ADDR: 1621 NE 20 AV

OWNER: PIEKARSKI, JASON
INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS.

- 1. THERE IS A CURRENT PERMIT# 15042829, FOR DOOR AND WINDOW REPLACEMENTS. IT APPEARS THAT THEY ARE WORKING BEYOND THE SCOPE OF THE ISSUED PERMIT AS THE BATHROOM AND KITCHEN HAVE RENOVATIONS IN PROGRESS.
- 2. WATER HEATER HAS BEEN REMOVED FROM ITS APPROVED LOCATION.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVEREED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE15061766
CASE ADDR: 1004 SW 7 ST
OWNER: SCHATZ, DAVID W
INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. PAVERS INSTALLATION ON DRIVEWAY.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE15062080
CASE ADDR: 4881 NW 9 TER
OWNER: CHARLES, ANNEMISE
INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

WINDOW OPENING WAS ENCLOSED.
 CENTRAL A/C UNIT WAS REPLACED.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITING PROCESS.

CASE NO: CE14071821 CASE ADDR: 1070 NW 25 AV OWNER: LANDERS, MARIE H/E

TAYLOR, MARTHA

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS:

- 1. SRT WORK DONE WITHOUT PERMITS. THIS PROPERTY HAS BEEN ALTERED BY THE OWNER ENCLOSING THE OPEN PORCH ON THE SOUTH SIDE OF THE DWELLING. IT IS BEING USED AS LIVING SPACE.(CMP)
- 2. THE WINDOWS WERE REPLACED IN THE OPENINGS.
- 3. STORAGE SHED WAS INSTALLED AT THE REAR OF THE DWELLING.
- 4. IN ADDITION, THE PROPERTY OWNER IS RENTING OUT ROOMS, INCLUDING THE ENCLOSED PORCH.

FBC(2010) 105.1.5

THE OWNERS ARE SELLING PREPARED FOOD TO THE PASSING PUBLIC FROM THE CARPORT.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

FBC(2010) 1604.1

THE STRUCTURES FOR THE ROOF AND WALLS BELONGING TO THE SOUTH SIDE ENCLOSED PORCH DO NOT MEET THE STANDARD FOR GRAVITY LOADING AND HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WIND LOADING THROUGH THE PERMITTING PROCESS. ALSO, THE ADDITION ON THE EAST SIDE OF THE BUILDING WHICH HOUSES A WATER HEATER IS NOT BUILT STRONG ENOUGH TO RESIST THE WIND AND GRAVITY LOADS THAT MAY BE IMPOSED. THE CONSTRUCTION METHODS AND MATERIALS DO NOT CONFORM TO ANY CODE.

ALL THE STRUCTURES THAT WERE DONE ILLEGALLY ARE DEEMED TO BE UNSAFE AS PER FBC 116.1.2 AND THE CONSTRUCTION IS UNDERDESIGNED. IT WOULD NOT PROVIDE THE REQUIRED RESISTANCE TO THE WIND'S UPLIFT.

CASE NO: CE14080903

CASE ADDR: 320 DELAWARE AVE

OWNER: 320 DELAWARE AVENUE INC

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS:

STOP WORK ISSUED.

- 1. THE NORTH WALLS FOOTING IS BEING REPAIRED.
- 2. FLOOR JOIST AND CEILING RAFTERS ARE BEING REPLACED.
- 3. THE EXISTING LIVING SPACE FLOOR LAYOUT IS BEING REDESIGNED WITH NEW FRAMING AND DRYWALL WORK.
- 4. A DUCTED CENTRAL A/C IS BEING INSTALLED.
- 5. INTERIOR ALTERATIONS OF THE ELECTRICAL AND PLUMBING SYSTEMS ARE BEING PERFORMED INSIDE THE DWELLING.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

FBC (2010) 115.1

ALL WORK IN PROGRESS MUST BE STOPPED UNTIL THE ENTIRE REQUIRED PERMITS ARE ISSUED.

CASE NO: CE14120489 CASE ADDR: 1633 NE 18 AV

OWNER: WIEDER, MATTHEW BRIAN

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS.

- 1. BUILDING AN OUTDOOR KITCHEN AREA IN THE BACK YARD UNDER A LARGE WOODEN TRELLIS.
- 2. PLUMBING AND ELECTRICAL WORK HAVE BEEN DONE TO PROVIDE THE FIXTURES WITH RUNNING WATER, DRAINAGE AND ELECTRICAL SERVICE.
- 3. LAYING PAVERS ON THE BACK PATIO.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE15020101
CASE ADDR: 1616 NW 16 ST
OWNER: RHA 2 LLC
INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS:

- 1. THE WINDOWS HAVE BEEN REPLACED ON THE DWELLING.
- 2. THE INTERIOR OF THE PROPERTY IS BEING GUTTED.
 ALTERATIONS TO THE EXISTING AND APPROVED FLOOR
 PLAN ARE ON THE WAY WITH THE REMOVAL OF
 PARTITIONS, ELECTRICAL AND PLUMBING IN THE WALLS.
 THEY ARE IN THE PROCESS OF BUILDING A NEW FLOOR
 LAYOUT OF THE DWELLING.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE15040555
CASE ADDR: 810 NE 4 AV
OWNER: R W L 4 INC
INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC (2010) 105.1

THIS BUILDING WAS APPROVED TO BE USED AS A WAREHOUSE. IT HAS BEEN ALTERED AND IS BEING USED AS A NIGHT CLUB. THERE IS AN OPEN BAR AND IT IS NOW A VENUE FOR MUSIC/COMEDY SHOWS.

- 1. SEVERAL WOOD STAGES WERE BUILT AT THE REAR AND THE BAR AREA.
- 2. ELECTRICAL LIGHTS WERE HUNG OVER THE OPEN YARD AND THE USE OF ELECTRICAL EXTENSIONS CORDS SUPPLYING POWER TO THE STAGE AREA.
- 3. THERE IS A KITCHEN AREA. THEY ARE NOT APPROVED TO SELL FOOD. A PERMIT IS REQUIRED AS PER FBC 105.1.5.
- 4. THE PARKING LOT AND THE TWO EXISTING BATHROOMS ARE NOT THE STANDARD REQUIREMENT OF THE ADA OR THE FBC ACCESSIBILITY.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

FBC (2010) 111.1.1

THE USE AND THE OCCUPANCY OF THIS BUILDING HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION FOR GROUP M TO AN ASSEMBLY GOUP A-2 OR A-3; WITHOUT OBTAINING THE REQUIRED PERMITS FOR A CHANGE OF USE AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT.

CASE NO: CE15110196
CASE ADDR: 1701 NW 14 CT
OWNER: 2771 LLC
INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2014) 105.3.1.4.18

THE FENCE AND GATE NEEDS TO HAVE A PROFESSIONAL DESIGNER'S DRAWINGS WITH THE WINDS PRESSURE CALCULATIONS OR THE NOA IF APPLICABLE AS PER FBC (2014) 2224.1 FOR CHAIN LINK AND FBC (2014) 2328.1 FOR WOOD FENCE, IT MUST SHOW THE SCOPE OF THE WORK WITH THE INSTALLATION DETAILS AND IT MUST

BE APPROVED BY ZONING TO BE INSTALLED ON THAT

LOCATION.

1. A WOOD FENCE WAS ERECTED AT THE PROPERTY

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE15102342
CASE ADDR: 1761 NW 26 TER
OWNER: AVIMAR TR

MARAVI LLC TRSTEE

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

FBC(2014) 105.3.1.4.18

THE FENCE AND GATE NEEDS TO HAVE A PROFESSIONAL DESIGNERS DRAWINGS WITH THE WINDS PRESSURE CALCULATIONS OR THE NOA IF APPLICABLE AS PER FBC(2014) 2224.1 FOR CHAIN LINK AND FBC(2014) 2328.1 FOR WOOD FENCE, IT MUST SHOW THE SCOPE OF THE WORK WITH THE INSTALLATION DETAILS AND IT MUST BE APPROVED BY ZONING TO BE INSTALLED ON THAT LOCATION.

1. A WOOD FENCE WAS ERECTED AROUND THE PROPERTY LOT.

CASE NO: CE15041350 CASE ADDR: 1162 NW 9 TER

OWNER: MERSAN HOLDINGS LLC

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS:

1. STRUCTURAL, PLUMBING AND ELECTRICAL ALTERATIONS ARE BEING DONE TO THE BUILDING. ALL THE WINDOWS AND DOORS WERE REPLACED IN THE OPENINGS.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITING AND INSPECTION PROCESS.

CASE NO: CE15041939

CASE ADDR: 1140 N FLAGLER DR OWNER: TANGALAKIS, HARRY G

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC (2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

FBC(2010) 111.1.1

THE USE AND THE OCCUPANCY OF THIS BUILDING HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION FOR GROUP M TO AN ASSEMBLY GROUP A-2 OR A-3; WITHOUT OBTAINING THE REQUIRED PERMITS FOR A CHANGE OF USE AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT.

FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS:

1. THIS BUILDING WAS APPROVED TO BE USED AS A WAREHOUSE. IT HAS BEEN ALTERED AND NOW IT IS A THEATRE. THEY HAVE AN OPEN AREA WITH A WOOD PLATFORM WITH CHAIRS TO SEAT OVER FIFTY PERSONS

AND THIS WAREHOUSE IS NOW A VENUE FOR DRAMA OR COMEDY SHOWS.

- 2. A WOOD PLATFORM AREA WAS BUILT AT THE REAR TO BE USED FOR THE LIGHT AND MUSIC DIRECTOR.
- 3. THE PARKING LOT, THE MAIN ENTRANCE, THE HALLWAY LEADING TO THE SEATING AREA AND THE TWO EXISTING BATHROOMS ARE NOT THE STANDARD REQUIREMENT FOR THE ADA OR FBC ACCESSIBILITY.
- 4. THERE ARE FLAMMABLE MATERIALS THAT WERE USED IN THE CONSTRUCTION OF THE STAGE AND THE LIGHTS. STAGE LAMPS WERE HUNG OVER THE OPEN CEILING WITH THE USE OF ELECTRICAL EXTENSIONS CORDS. IN CASE OF A FIRE, THE FLAMES CAN FREELY MOVE FROM ONE AREA OF THE WAREHOUSE TO THE OTHER WITHOUT BEING STOPPED BY A FIRE PARTITION OR BARRIERS.

FBC(2010) 105.4.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

- 1. ALTERATIONS WERE DONE TO THE ELECTRICAL SYSTEM TO POWER ALL THE LAMPS AND STAGE LIGHTS.
- 2. THE LIGHTS ARE BEING SUPPLIED FROM THE WALL OUTLETS WITH POWER OR EXTENSION CORDS. BY THIS ACTION THE OWNER IS INCREASING THE AMPERAGE LOAD IN THE MAIN ELECTRICAL PANEL OVER THE TOTAL AMPS LOAD RATING THAT WAS PERMITTED. IT HAS BECOME AN ELECTRICAL FIRE HAZARD.

CASE NO: CE13061394 CASE ADDR: 6837 NW 29 AV

OWNER: US BANK NATIONAL ASSN TRSTEE

NEW OWNERS: JAZHAM HOMES LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED

PERMITS AND INSPECTIONS:

1. THE OWNER ADDED A 2ND FLOOR BATHROOM ILLEGALLY.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT OBTAINING THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE14081054

CASE ADDR: 1834 LAUD MANORS DR OWNER: WSC BRICKELL LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS AS FOLLOWS:

- 1. WINDOWS AND EXTERIOR DOORS WERE REPLACED.
- 2. THE DWELLING WAS RE-ROOFED.
- 3. THE EXISTING CARPORT THAT WAS BUILT WITH THE DWELLING WAS ENCLOSED INTO A LIVING SPACE.
- 4. A DUCTED CENTRAL A/C WAS INSTALLED.
- 5. INTERIOR RENOVATIONS AND ELECTRICAL AND PLUMBING UPGRADES WERE PERFORMED INSIDE THE KITCHEN AND BATHROOMS.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE14100834 CASE ADDR: 3601 SW 2 ST

OWNER: GRAHAM, VINCENT M & JACQUELINE

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. ADDITION 784 SF 1STY

FAMILYROOM/BATHROOM/PLAYROOM.

2. ROOF FOR ADDITION.

FBC(2010) 105.4.11

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF THE MECHANICAL COMPONENTS AND/OR MODIFYING THE MECHANICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING CONDENSER UNITS, EVAPORATOR UNITS, DUCTWORK, ELECTRICAL COMPONENTS, THERMOSTATS, COOLING TOWERS, HEATERS, AND OTHER MECHANICAL COMPONENTS

CONNECTED TO THE MECHANICAL SYSTEM.

THE MECHANICAL SYSTEM OF THE BUILDING HAS BEEN
ALTERED OR CHANGED WITHOUT OBTAINING A PERMIT IN
THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:
1. MECHANICAL FOR ADDITION.

FBC(2010) 105.4.4

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF PLUMBING COMPONENTS AND/OR MODIFYING THE PLUMBING SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING PLUMBING COMPONENTS THAT MAY INCLUDE PLUMBING FIXTURES SUCH AS VALVES, TOILETS, SINKS, DIVERTERS, SHOWER HEADS, WATER SPIGOTS, WATER LINES, WASTE DISPOSAL PIPES, WATER HEATERS, SOLAR PANELS, IRRIGATION SYSTEM, PUMPS AND OTHER PLUMBING COMPONENTS CONNECTED THE PLUMBING SYSTEM.

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. PLUMBING FOR ADDITION.

FBC(2010) 105.4.5

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF ELECTRICAL COMPONENTS AND/OR MODIFYING THE ELECTRICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING ELECTRICAL COMPONENTS THAT MAY INCLUDE SWITCHES, OUTLETS, ELECTRICAL FIXTURES, BREAKER/PANEL BOXES, METER BASES, WIRES, REWIRING AND OTHER ELECTRICAL COMPONENTS CONNECTED TO THE ELECTRICAL SYSTEM.

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. ELECTRIC FOR ADDITION.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE14111191

CASE ADDR: 5955 NW 31 AVE # A
OWNER: LAKEVIEW PLAZA INC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. INTERIOR RENOVATION OF WALL PARTITIONS.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITING PROCESS.

CASE NO: CE15011130

CASE ADDR: 951 ALABAMA AVE

OWNER: TROPNEVAD PROMOTIONS LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITING PROCESS.

FBC 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. ATTACHED ADDITIONS AND INTERIOR RENOVATIONS.

CASE NO: CE15031679
CASE ADDR: 1501 NW 19 AVE
OWNER: GRANT FLA LLC
INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED

PERMITS AND INSPECTIONS:

- 1. FLORIDA ROOM WAS CONVERTED INTO A THIRD BEDROOM WITH A BATHROOM. THERE ARE 15 PEOPLE LIVING IN THE DWELLING AS PER CODE OFFICER QUINTERO.
- 2. THERE ARE NEW WINDOWS AND DOORS INSTALLED OR REPLACED ON THE PROPERTY.
- 3. A CENTRAL A/C SYSTEM UNIT INSTALLED.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE15042161 CASE ADDR: 2505 NW 20 ST OWNER: IRVIN, DOROTHY H

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. CONSTRUCTION HAS CONTINUED WITH EXPIRED PERMITS.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITING PROCESS.

CASE NO: CE15050398 CASE ADDR: 1216 NE 16 AVE

OWNER: BENNETT, RONALD D & JILLIAN S

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. THE BUILDING HAS BEEN ALTERED FROM A DUPLEX TO TRIPLEX WITHOUT A PERMIT. ALTERATIONS ARE NOT LIMITED TO STRUCTURAL, PLUMBING, ELECTRICAL AND MECHANICAL.

FBC(2010) 105.4.11

THE MECHANICAL SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. THE MECHANICAL SYSTEM HAS BEEN ALTERED TO ACCOMMODATE ILLEGAL USE AS A TRIPLEX WITHOUT A PERMIT.

FBC (2010) 105.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. ALTERATIONS OF PLUMBING SYSTEM TO ACCOMMODATE THE ILLEGAL USE AS A TRIPLEX WITHOUT OBTAINING THE REQUIRED PERMITS.

FBC(2010) 105.4.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. THE ELECTRICAL SYSTEM HAS BEEN ALTERED TO ACCOMMODATE ILLEGAL USE AS A TRIPLEX WITHOUT A PERMIT.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITING PROCESS.

FBC(2010) 111.1.1

THE USE AND THE OCCUPANCY OF THIS DWELLING HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED

OCCUPANCY CLASSIFICATION OF A DUPLEX TO A TRIPLEX WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT.

UNDER FBC(2010) 116.2.1.3.2 BY REASON OF ILLEGAL OR IMPROPER USE, OCCUPANCY, OR MAINTENANCE DOES NOT COMPLY WITH THIS CODE OR THE CODE IN EFFECT AT THE TIME OF CONSTRUCTION OR THE APPLICABLE MINIMUM HOUSING CODE. THE STRUCTURE IS DEEMED TO BE UNSAFE UNDER THIS SECTION OF THE CODE.

CASE NO: CE15051829
CASE ADDR: 1804 NW 16 CT
OWNER: TUCHOW, TYLER
INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. THE CARPORT HAS BEEN ENCLOSED.
- 2. PLUMBING, ELECTRICAL & MECHANICAL WORK HAVE BEEN DONE WITHIN THE ENCLOSED CARPORT FOR A BATHROOM AND WASHER AND DRYER .

FBC(2010) 105.4.5

THE ELECTRICAL IN THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. ELECTRICAL SUPPLYING THE ENCLOSED CARPORT.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

FBC(2010) 111.1.1

USE AND OCCUPANCY. NO BUILDING OR STRUCTURE SHALL BE USED OR OCCUPIED, AND NO CHANGE IN THE EXISTING OCCUPANCY CLASSIFICATION OF A BUILDING OR STRUCTURE OR NATURE OR USE OR PORTION THEREOF SHALL BE MADE UNTIL THE BUILDING OFFICIAL HAS ISSUED A CERTIFICATE OF OCCUPANCY THERE FOR AS PROVIDED HEREIN. SAID CERTIFICATE SHALL NOT BE

ISSUED UNTIL ALL REQUIRED ELECTRICAL, GAS,
MECHANICAL, PLUMBING AND FIRE PROTECTION SYSTEMS,
AND PROVISIONS OF FFPC HAVE BEEN INSPECTED FOR
COMPLIANCE WITH THE TECHNICAL CODES AND OTHER
APPLICABLE LAWS AND ORDINANCES AND RELEASED BY THE
BUILDING OFFICIAL. ISSUANCE OF A CERTIFICATE OF
OCCUPANCY SHALL NOT BE CONSTRUED AS AN APPROVAL OF
A VIOLATION OF THE PROVISIONS OF THIS CODE OR OF
OTHER ORDINANCES OF THE JURISDICTION.

CASE NO: CE15070098
CASE ADDR: 5200 NW 31 AVE

OWNER: VILLAS AT LAKEVIEW CONDO ASSN INC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. BUILT STORAGE SHEDS ON PROPERTY WITHOUT OBTAINING THE REQUIRED PERMITS.

FBC(2014) 105.3.1.4.18

INSTALLED WOOD FENCE WITHOUT OBTAINING THE REOUIRED PERMITS.

FBC(2014) 105.3.1.4.4

INSTALLED WATER SUPPLY LINES/SPRINKLER/SEWER LINES WITHOUT OBTAINING THE REQUIRED PERMITS.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE15070731
CASE ADDR: 1119 NW 10 PL
OWNER: ADAMS MEM LLC
INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. CONVERTED FROM 2/1 INTO A 3/2.
- 2. CONVERTED UTILITY ROOM INTO A BATHROOM.

FBC(2014) 105.3.1.4.11

THE MECHANICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED OR CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. INSTALLED A SPLIT A/C SYSTEM.

FBC(2014) 105.3.1.4.4

ALTERING, REPAIRING, INSTALLATION OF PLUMBING COMPONENTS AND/OR MODIFYING THE PLUMBING SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS. INSTALLATION AND MODIFICATION BUT NOT LIMITED TO:

1. INSTALLED FIXTURES IN CONVERTED BATHROOM. INSTALLED WATER HEATER.

FBC(2014) 105.3.1.4.5

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF ELECTRICAL COMPONENTS AND/OR MODIFYING THE ELECTRICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING ELECTRICAL COMPONENTS THAT MAY INCLUDE SWITCHES, OUTLETS, ELECTRICAL FIXTURES, BREAKER/PANEL BOXES, METER BASES, WIRES, REWIRING AND OTHER ELECTRICAL COMPONENTS CONNECTED TO THE ELECTRICAL SYSTEM. THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. ALTERED ELECTRICAL SYSTEM AND THERE ILLEGAL ELECTRICAL CONNECTIONS UNDER THE KITCHEN SINK. WATER HEATER THAT WHEN IN USE THE BREAKERS GET VERY HOT.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITING PROCESS.

CASE NO: CE15070738

CASE ADDR: 1301 NE 2 AV

OWNER: SETTON, JOHN

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. RE-ROOFING WITH NO PERMIT.

FBC(2014) 105.3.1.4.10 REQUIREMENTS FOR ROOF PERMIT.

FBC(2014) 105.3.1.4.15

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLED WINDOWS WITHOUT PERMIT.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVER-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPT, THROUGHOUT THE PERMITING PROCESS.

CASE NO: CE15070837
CASE ADDR: 1631 NW 26 TER
OWNER: MOORE, CARLTON EST

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 1029.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. DOORS HAVE BEEN BLOCKED BY THE INSTALLATION OF DEVICE(S) REQUIRING A KEY/TOOL TO OPERATE.

FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. HOME ALTERED AND CONVERTED TO ROOMING HOUSE WITHOUT PERMIT.
- 2. KITCHEN HAS BEEN REMODELED.

FBC(2014) 105.3.1.4.4

ALTERING, REPAIRING, INSTALLATION OF PLUMBING COMPONENTS AND/OR MODIFYING THE PLUMBING SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS. INSTALLATION AND MODIFICATION BUT NOT LIMITED TO:

1. KITCHEN HAS BEEN REMODELED AND THE PLUMBING SYSTEM HAS BEEN ALTERED AND/MODIFIED, BUT NOT LIMITED TO THE REMOVAL AND INSTALLATION OF FIXTURES.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

FBC (2014) 111.1.1

THE USE AND THE OCCUPANCY OF THIS DWELLING HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION OF A SINGLE FAMILY HOME TO A ROOMING HOUSE WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT.

CASE NO: CE15071162
CASE ADDR: 1034 NW 11 CT
OWNER: BING, LATRICE E
INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS DWELLING HAD A PERMIT TO BUILD AN ADDITION FROM FEBRUARY 2005 AND IT WAS LEFT TO EXPIRE. TODAY THESE PERMITS ARE NULL AND VOID AS PER FBC(2014) 105.3.2.1. THIS WORK HAS BECOME WORK WITHOUT A PERMIT AND IS DEEMED TO BE UNSAFE UNDER SUB SECTION FBC(2014) 116.2.1.3.1 - THIS BUILDING IS BEING USED AND OCCUPIED WITHOUT THE PROPER CERTIFICATE OF OCCUPANCY FROM THE CITY.

- 1. P#05021695 Expired BADDRSM 1034 NW 11 CT BING, LATRICE E ADDITION TO SF RES.
- 2. P#06112272 Expired ERESADD 1034 NW 11 CT BING, LATRICE E ELECTRICAL FOR ADDITION BP 05021695
- 3. P#06112275 Expired PPLUMSFRNU 1034 NW 11 CT BING, LATRICE E PLUMBING FOR ADDITION BP 05021695

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITING AND INSPECTION PROCESS.

FBC(2014) 111.4.1

THE BUILDING MUST BE VACATED UNTIL IS IN COMPLIACE WITH THE MINIMUM HOUSING CODE SEC.9-240 AND FBC 111.1.1 FOR THE EXTENSIVE BUILDING ALTERATIONS OR EXPANSIONS THAT WERE DONE WITHOUT OBTAINING THE FINAL INSPECTIONS FOR THE BUILDING, ELECTRICAL, MECHANICAL AND PLUMBING PERMITS THAT WERE LEFT TO EXPIRE FOR THE PERFORMED ALTERATIONS. ALSO THE REQUIRED CERTIFICATE OF OCCUPANCY HAS NOT BEEN ISSUED AND THIS PROPERTY IS BEING USED BY THE OWNER.

CASE NO: CE15072597 CASE ADDR: 215 SW 19 AV

OWNER: ROBERTSON PARK APARTMENTS LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.3.1.4.11

THE MECHANICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED OR CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED

1. THERE WERE 4 A/C PACKAGE UNITS INSTALLED WITHOUT A PERMIT. PERMIT HISTORY SHOWS NO MECHANICAL PERMITS TO INDICATE APPROVED INSTALLATION.

UNIT 1: MANUFACTURE DATE 10/2013

SERIAL NUMBER 1310067960

UNIT 2: MANUFACTURE DATE 04/2006

SERIAL NUMBER 0604606627

UNIT 3: MANUFACTURE DATE 05/2009

SERIAL NUMBER 0905655982

UNIT 4: MANUFACTURE DATE 05/2014

SERIAL NUMBER 1405639754

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITING PROCESS.

CASE NO: CE15080366 CASE ADDR: 6980 NW 29 WY

OWNER: SFS INVESTMENTS LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. STUCCO AND FASCIA BOARDS REPLACED WITHOUT A

PERMIT.

FBC(2014) 105.3.1.4.10

ROOF REPAIRED WITHOUT A PERMIT.

FBC(2014) 105.3.1.4.18

FENCE AND GATES REPAIRED WITHOUT A PERMIT.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITING PROCESS.

CASE NO: CE15081360
CASE ADDR: 621 SE 5 CT
OWNER: BLUEWATER INC
INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. DRIVEWAY PAVERS INSTALLED WITHOUT A PERMIT.

FBC(2014) 105.3.1.4.18

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. FENCE INSTALLED WITHOUT A PERMIT.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE15082061

CASE ADDR: 86 ISLE OF VENICE
OWNER: SANTIAGO'S HOUSE LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. INSTALLED NEW WOOD DECK WITHOUT OBTAINING THE

REQUIRED PERMTS.

FBC(2014) 105.3.1.4.15

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLED WINDOWS AND DOORS WITHOUT OBTAINING THE REQUIRED PERMITS.

FBC (2014) 105.3.1.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLED NEW TOILET FIXTURE WITHOUT OBTAINING THE REQUIRED PERMIT. IT IS NOW BACKED UP AND UNSANITARY.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITING PROCESS.

CASE NO: CE15082209
CASE ADDR: 724 NW 17 ST

OWNER: SHUTTS, JASON ALBERT

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. CONSTRUCTED A STUDIO APARTMENT WITHOUT THE REQUIRED PERMITS.

FBC(2014) 105.3.1.4.4

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. THE PLUMBING SYSTEM HAS BEEN ALTERED TO ACCOMODATE THE ILLEGAL CONVERSION OF A STUDIO APARTMENT WITHOUT THE REQUIRED PERMIT.

FBC(2014) 105.3.1.4.5

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. THE ELECTRICAL SYSTEM HAS BEEN ALTERED TO ACCOMODATE THE ILLEGAL CONVERSION OF A STUDIO APARTMENT WITHOUT THE REQUIRED PERMIT.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

FBC(2014) 111.1.1

THE USE AND THE OCCUPANCY OF THIS DWELLING HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION OF A DUPLEX TO A FOURPLEX WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT.

CONVERTED PART OF THE BUILDING TO A STUDIO APARTMENT.

CASE NO: CE15090899 CASE ADDR: 1425 SW 10 ST

OWNER: 2015-3 IH2 BORROWER LP

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. ENCLOSED CARPORT WITHOUT OBTAINING THE REQUIRED PERMIT.

FBC(2014) 105.3.1.4.15

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLED WINDOW AT CARPORT ENCLOSURE WITHOUT THE REQUIRED PERMIT.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE15092128
CASE ADDR: 216 NW 8 AVE

OWNER: VILLANUEVA, ROBERTO

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INTERIOR HAS BEEN GUTTED AND HOME IS BEING REMODELED.

FBC(2014) 105.3.1.4.15

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLATION OF WINDOWS AND DOORS.

FBC(2014) 105.3.1.4.18

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLATION OF FENCE WITHOUT HAVING PERMIT ISSUED.

FBC(2014) 105.3.1.4.4

ALTERING, REPAIRING, INSTALLATION OF PLUMBING COMPONENTS AND/OR MODIFYING THE PLUMBING SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS. INSTALLATION AND MODIFICATION BUT NOT LIMITED TO: 1. INTALLATION OF NEW PLUMBING INCLUDING FIXTURES.

FBC(2014) 105.3.1.4.5

ALTERING, REPAIRING, INSTALLATION OF ELECTRICAL COMPONENTS AND/OR MODIFYING THE ELECTRICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS BUT NOT LIMITED TO:

1. INSTALLATION OF WIRING, SWITCHES, OUTLETS, BOXES AND BREAKERS.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITING PROCESS.

FBC(2014) 115.1

STOP WORK ORDER ISSUED SINCE WORK IS ONGOING WITHOUT THE REQUIRED PERMITS.

HEARING TO IMPOSE FINES

CHAPTER 11, FORT LAUDERDALE CODE OF ORDINANCES

CASE NO: CE08070448
CASE ADDR: 1431 NW 11 PL

OWNER: DRAGOSLAVIC, GORAN

DRAGOSLAVIC, TERESA

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC (2007) 105.1

THE PROPERTY SUSTAINED MAJOR DAMAGE TO THE STRUCTURE AND THE INTERIOR CAUSED BY A FIRE BACK

ON JULY 7, 2008.

A STOP WORK ORDER WAS ISSUED ON JULY 11, 2011 FOR WORK IN PROGRESS. ALL THE REPAIRS WERE PERFORMED

WITHOUT OBTAINING THE REQUIRED PERMITS AND

INSPECTIONS:

1. THE ELECTRICAL SYSTEM WAS DAMAGED AND IT HAS BEEN REPAIRED.

- 2. THE FAMILY ROOM CEILING RAFTERS WITH THE ROOF DECK WERE COMPLETELY BURNED AWAY. THEY HAVE BEEN REPLACED.
- 3. COMPLETE INTERIOR RESTORATION: ALL THE ELECTRICAL AND PLUMBING FIXTURES, THE DRYWALL ON THE CEILING AND WALLS, WITH ALL THE CABINETRY WERE REPLACED.
- 4. THE AIR CONDITIONING SYSTEM HAS BEEN REPLACED IN WHOLE OR IN PART FROM THE FIRE DAMAGE.

FBC(2007) 109.10

WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REOUIRED APPROVALS.

CASE NO: CE15090051 CASE ADDR: 1216 NE 2 ST

OWNER: MAUS, ARTHUR J & KAREN N

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2014) 105.3.2.1

THE FOLLOWING PERMITS WERE LEFT TO EXPIRE AND THE POOL CONSTRUCTION WAS FINISHED. TODAY IT REMAINS

WORK WITHOUT PERMITS. IT IS A LIFE SAFETY VIOLATION DUE TO THE FACT THAT THE ELECTRICAL SYSTEM HAS NOTT BEEN FINALED AND THE CHILD

BARRIERS HAVE NOT BEEN APPROVED TO COMPLY WITH THE

FLORIDA CHILD PROTECTION ACT FS515.

1. ELECTRICAL PERMIT # 00070898 (WIRE IN PUMP MOTOR, POOL LIGHT, GROUNDING).

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE11061307
CASE ADDR: 2021 NE 59 ST

OWNER: LANE, CHRISTOPHER E & WENDY B

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. THE GARAGE HAS BEEN ENCLOSED AND HAS BEEN CONVERTED TO LIVING SPACE.
- 2. THE GARAGE HAS BEEN ENCLOSED.
- 3. WINDOWS HAVE BEEN INSTALLED.
- 4. INTERIOR FRAMING AND DRYWALL HAVE BEEN INSTALLED.

FBC (2007) 105.4.11

THE MECHANICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

1. THE ENCLOSED GARAGE HAS BEEN AIR CONDITIONED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

1. PIPING AND FIXTURES HAVE BEEN INSTALLED DURING THE GARAGE ENCLOSURE.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

1.CIRCUITS HAVE BEEN ADDED/ALTERED DURING THE GARAGE ENCLOSURE.

FBC(2007) 109.10

WORK WAS PERFORMED AND/OR COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC(2007) 1612.1.2

THE ENCLOSED GARAGE OPENING, THE WINDOWS INSTALLED, AND THE AC UNIT, IF INSTALLED, HAVE NOT BEEN PROVEN TO SUFFICIENTLY WITHSTAND ESTIMATED OR ACTUAL IMPOSED DEAD, LIVE, WIND, OR ANY OTHER LOADS THROUGH THE PERMIT AND INSPECTION PROCESS.

CASE NO: CE14031507 CASE ADDR: 416 SW 11 CT

OWNER: REYNOLDS, STUART L

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.1

- 1. THE PROPERTY OWNER HAS CONVERTED THIS SINGLE FAMILY HOUSE INTO A DUPLEX RENTING OUT THE BACK AND FRONT TO TWO DIFFERENT FAMILIES. THEY HAVE ENCLOSED THE CARPORT AND HALLWAY LEADING TO ONE PART OF THE HOUSE TO CREATE THE NEW FLOOR PLAN.
- 2. THEY HAVE ADDED ELECTRIC OUTLETS AND PLUMBING FIXTURES IN THE ENCLOSED CARPORT.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

FBC(2010) 111.1.1

THE USE AND THE OCCUPANCY OF THE CARPORT HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION CLASS U (UTILITY) TO R-3 (LIVING SPACE) WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT.

CASE NO: CE14050728 CASE ADDR: 2840 NE 25 ST

OWNER: CLEMENTE, DANIELA VALENTI

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. BUILT DOCK.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITING PROCESS.

CASE NO: CE14071684
CASE ADDR: 1608 SW 10 CT
OWNER: SOFREI LLC
INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS:

- 1. INTERIOR ALTERATIONS OF THE ELECTRICAL, PLUMBING AND MECHANICAL SYSTEMS.
- 2. DRYWALL REPLACEMENT INSIDE THE KITCHEN AND BATHROOMS AREAS.
- 3. THE WINDOWS AND EXTERIOR DOORS WERE REPLACED.
- 4. THE PROPERTY WAS RE-ROOFED WITH SHINGLES. THE PERMIT WAS LEFT TO EXPIRE WITHOUT PASSING FINAL INSPECTIONS. TODAY IT REMAINS WORK WITHOUT PERMITS.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE14091251 CASE ADDR: 1736 SE 14 ST OWNER: VERDUGO, CARLOS E INSPECTOR: ROBERT MASULA

VIOLATIONS: 9-280(b)

- 1. THERE ARE BUILDING PARTS WHICH ARE DETERIORATED AND NOT MAINTAINED.
- 2. THE SEAWALL AT THIS PROPERTY IS IN NEED OF REPAIRS AND MAINTENANCE.

FBC(2010) 105.4.18

THIS PROPERTY HAS BEEN ALTERED WITH THE INSTALLATION OF A FENCE WITHOUT THE REQUIRED PERMIT AND/OR INSPECTIONS.

FBC(2010) 105.4.3

- 1. THIS PROPERTY HAS BEEN ALTERED WITH THE PARTIAL DEMOLITION OF A DOCK WITHOUT THE REOUIRED PERMIT AND/OR INSPECTIONS.
- 2. THE WOODEN DOCK HAS NOT BEEN MAINTAINED AND HAS NOW DETERIORATED FROM THE ELEMENTS. THIS STRUCTURE HAS NOW BECOME A WINDSTORM HAZARD AND IS UNSAFE.

CASE NO: CE14111609

CASE ADDR: 545 S FTL BEACH BLVD 1101

OWNER: WISMER, GERALD BRUCE

NEW OWNER: BRENNAN, MICHAEL INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS CONDO UNIT HAS BEEN ALTERED WITH THE INTERIOR REMODELING WITHOUT THE REQUIRED STRUCTURAL PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.3

THIS CONDO UNIT HAS BEEN ALTERED WITH THE INTERIOR DEMOLITION OF THE FRAMING AND DRYWALL THROUGHOUT THE KITCHEN, BATHROOMS, AND OTHER AREAS OF THIS UNIT WITHOUT THE REQUIRED DEMOLITION PERMITS

AND/OR INSPECTIONS.

FBC(2010) 105.4.4

THIS CONDO UNIT HAS BEEN ALTERED WITH THE REMOVAL OF THE PLUMBING FIXTURES IN THE KITCHEN AND BATHROOMS WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2010) 105.4.5

THIS CONDO UNIT HAS BEEN ALTERED WITH THE ALTERATION OF ELECTRICAL WIRING AND DEVICES WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2010) 110.9

THIS CODE CASE WILL REQUIRE THAT ALL REQUIRED PERMITS ARE OBTAINED, INSPECTED, PASSED AND CLOSED IN ORDER TO COMPLY AND CLOSE THIS CODE CASE IN THIS CONDO BUILDING.

CASE NO: CE14121723
CASE ADDR: 2879 NE 28 ST
OWNER: NOLAN, GERALD N
INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS PROPERTY HAS BEEN ALTERED WITH THE SUB-DIVISION OF THE HOUSE TO CREATE SEPARATE RENTAL UNITS WITHOUT OBTAINING THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.11

THIS PROPERTY HAS BEEN ALTERED WITH THE REMOVAL AND REPLACEMENT OF THE MAIN A/C UNIT WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.4

THIS PROPERTY HAS BEEN ALTERED WITH THE REMOVAL AND REPLACEMENT OF PLUMBING FIXTURES WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.5

THIS PROPERTY HAS BEEN ALTERED BY ADDING ELECTRICAL WIRING, DEVICES AND FIXTURES WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 110.9

THIS CODE CASE WILL REQUIRE THAT PERMITS BE OBTAINED, INSPECTED, PASSED AND CLOSED PRIOR TO COMPLYING AND CLOSING THIS CASE.

FBC(2010) 111.1.1

THIS CODE CASE WILL REQUIRE A NEW CERTIFICATE OF OCCUPANCY IF THIS HOUSE IS SUBDIVIDED INTO SEPARATE RENTAL UNITS.

CASE NO: CE15011944
CASE ADDR: 609 NE 8 AV

OWNER: ELITE HOME PARTNERS LLC

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC (2010) 105.1

THIS PROPERTY HAS BEEN ALTERED WITH INTERIOR AND EXTERIOR RENOVATIONS WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.15

THIS PROPERTY HAS BEEN ALTERED WITH THE REPLACEMENT OF THE FRONT DOOR WITHOUT THE REQUIRED PERMIT AND/OR INSPECTIONS.

FBC(2010) 105.4.17

THIS PROPERTY HAS BEEN ALTERED WITH THE REPLACEMENT OF THE GARAGE DOOR WITHOUT THE REQUIRED PERMIT AND/OR INSPECTIONS.

FBC(2010) 110.9

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE AFTER THE FACT PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE OUT ALL REQUIRED PERMITS BEFORE THIS CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15020287

CASE ADDR: 3233 NE 34 ST # 1612

OWNER: CRICKETT, JOHN J INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS CONDO UNIT HAS BEEN ALTERED WITH THE STRUCTURAL WORK OF INTERIOR WALL FRAMING WITH REGULAR WHITE LUMBER (COMBUSTIBLE MATERIALS) AND DRYWALL INSTALLED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.4

THIS CONDO UNIT HAS BEEN ALTERED WITH THE REMOVAL OF THE PLUMBING FIXTURES IN TWO BATHROOMS WITHOUT THE REQUIRED PERMIT AND/OR INSPECTIONS.

FBC(2010) 105.4.5

THIS CONDO UNIT HAS BEEN ALTERED WITH THE DEMOLITION OF ELECTRICAL, THE ILLEGAL WIRING OF ROMEX WIRING INSTALLED, ELECTRICAL BOXES INSTALLED, ELECTRICAL WIRES CUT FROM INSIDE METAL CONDUIT AND ELECTRICAL ALTERATIONS WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.11

THIS CONDO UNIT HAS BEEN ALTERED WITH THE INSTALLATION OF MECHANICAL DUCT WORK WITHOUT THE REQUIRED PERMIT AND/OR INSPECTIONS.

FBC(2010) 110.9

THE OWNER OF THIS CONDO UNIT WILL BE REQUIRED TO OBTAIN ARCHITECTURAL DRAWINGS BECAUSE OF THE SEVERITY OF THE VIOLATIONS, OBTAIN ALL REQUIRED PERMITS, SCHEDULE AND PASS ALL REQUIRED INSPECTIONS, PROPERLY CLOSE OUT ALL THE REQUIRED PERMITS IN ORDER TO FULLY COMPLY AND CLOSE THIS CODE CASE.

CASE NO: CE15080187

CASE ADDR: 2933 POINSETTIA ST

OWNER: CORTEZ PROPERTY DEV LLC

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2014) 116.1.1

- 1. THERE ARE LIGHT FIXTURES MISSING IN THE WALKWAYS AND STAIRWELLS OF THIS BUILDING. THISIS A VIOLATION UNDER THE MINIMUM HOUSING CODE.
- 2. THERE ARE UNITS IN THIS BUILDING WHERE THE KITCHENS AND BATHROOMS HAVE BEEN PARTIALLY DEMOLISHED OR COMPLETELY DEMOLISHEDED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS. THIS IS ALSO A VIOLATION UNDER THE MINIMUM HOUSING CODE.
- 3. THE STAIRWELL ON THE NORTH END OF THE BUILDING LEADING TO THE ROOFTOP AREA HAS BEEN CLOSED OFF, FRAMED, SHEATHING AND STUCCOED OVER WITHOUT THE REQUIRED PERMITS AND/ OR INSPECTIONS.
- 4. THERE ARE RENTAL UNITS IN THIS BUILDING THAT HAVE HAD KITCHENS AND BATHROOMS REMODELED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.
- 5. THE LOW VOLTAGE ELECTRICAL BOX ON THE GROUND FLOOR IN THE GARAGE AREA IS IN DISREPAIR. WIRING IS EXPOSED AND HANGING LOOSE. THIS IS AN ELECTRICAL CODE VIOLATION AND A MAINTENANCE VIOLATION.
- 6. THERE ARE ILLEGAL FIRE DOORS THAT HAVE BEEN INSTALLED IN THE STAIRWELLS AND THE ENTRY DOORS OF THE UNITS WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS. THIS IS ALSO A FIRE CODE VIOLATION.
- 7. THE ILLEGAL UNIT ON THE ROOF TOP HAS A PATIO AREA WHICH HAS NO BALCONY RAILING IN PLACE AND IS A FOUR STORY DROP. THIS IS A LIFE SAFETY ISSUE.
- 8. THERE ARE ELECTRICAL PANELS THAT HAVE NOT BEEN MAINTAINED AND ALSO HAVE MISSING BREAKERS. THIS IS AN ELECTRICAL CODE VIOLATION AND ALSO A POTENTIAL LIFE SAFETY ISSUE.
- 9. THERE ARE ELECTRICAL BOXES AND OUTLETS THAT ARE ROTTED OUT AND IN NEED OF REPLACEMENT. THIS IS AN ELECTRICAL CODE VIOLATION.
- 10. THERE ARE STAIRWELL DOORS WHICH THE DOOR CLOSERS DO NOT CLOSE THE DOOR PROPERLY AND THE DOORS THEMSELVES DO NOT CLOSE PROPERLY. THIS IS A MAINTENANCE AND FIRE CODE VIOLATION.

FBC(2014) 116.1.2

1. THERE IS AN ILLEGAL ROOF TOP ADDITION THAT IS CURRENTLY ADVISED AS A STUDIO RENTAL. THIS ILLEGAL ROOF TOP ADDITION WAS A CODE CASE FROM OCTOBER 22ND, 2002. PERMIT 03060376 WAS APPLIED FOR ON 06-05-2003, FAILED PLAN REVIEW. THE PERMIT WAS NEVER ISSUED AND THE APPLICATION WAS PURGED FROM OUR SYSTEM ON NOVEMBER 21, 2003.

FBC(2014) 116.2.1.1.2

1. THERE IS AN UNWARRANTED ACCUMULATION OF DEBRIS AND OTHER COMBUSTIBLE MATERIAL WHICH INCLUDES BUT IS NOT LIMITED TO: COUCHES, FUEL CONTAINERS, SCREEN DOORS, ABANDONED VEHICLES, PAINT CANS AND LUMBER. THIS IS A POTENTIAL FIRE HAZARD.

FBC(2014) 116.2.1.1.3

- 1. NFPA 1:13.6.9.3.1.1.1 OUT FE 05/14
 TO WIT: THE FIRE EXTINGUISHER(S) HAS/HAVE NOT BEEN
 SERVICED AND TAGGED BY A STATE LICENSED COMPANY
 WITHIN THE PAST 12 MONTHS.
 CORRECTIVE ACTION: HAVE THE FIRE EXTINGUISHER(S)
 SERVICED AND TAGGED BY A STATE LICENSED COMPANY.
- 2. NFPA 101:7.9.2.1 SERVICE ALL EMERGENCY LIGHTS. TO WIT: THE EMERGENCY LIGHT DOES NOT ILLUMINATE AS DESIGNED.

 CORRECTIVE ACTION: REPAIR THE EMERGENCY LIGHT TO ILLUMINATE AS DESIGNED.
- 3. NFPA 101:7.10.5.2.1 SERVICE ALL EXIT SIGNS. TO WIT: THE EXIT SIGN DOES NOT ILLUMINATE AS DESIGNED.

 CORRECTIVE ACTION: REPAIR THE EXIT SIGN TO ILLUMINATE AS DESIGNED.
- 4. NFPA 1:10.11.6 REMOVE ALL GRILLS FROM STRUCTURE.

TO WIT: A(AN) HIBACHI, GRILL, OR OTHER SIMILAR DEVICE(S) USED FOR COOKING, HEATING, OR ANY OTHER PURPOSE IS BEING USED OR KINDLED ON A BALCONY, UNDER A OVERHANGING PORTION, OR WITHIN 10 FT (3 M) OF A STRUCTURE.

CORRECTIVE ACTION: DISCONTINUE THE USE OF AND REMOVE THE HIBACHI, GRILL, OR OTHER SIMILAR DEVICES USED FOR COOKING, HEATING, OR ANY OTHER PURPOSE THAT IS BEING USED OR KINDLED ON A BALCONY, UNDER AN OVERHANGING PORTION, OR WITHIN

10 FT (3 M) OF THE STRUCTURE.

5. NFPA 1:1.7.6.2 FIX F/A REPAIR THE FIRE ALARM SYSTEM.

TO WIT: THE FIRE ALARM SYSTEM APPEARS TO HAVE NO POWER AND IS NOT FUNCTIONAL AT THIS TIME. NO ACCESS TO THE ELECTRIC METER ROOM TO VERIFY THIS CONDITION. PROVIDE ACCESS.

CORRECTIVE ACTION: REPAIR THE FIRE ALARM ASAP AND PROVIDE ACCESS TO THE ELECTRIC METER ROOM TO VERIFY THE CONDITION OF THE BUILDING FIRE ALARM SYSTEM.

6. NFPA 101:31.3.4.5.1 REPAIR ALL SMOKE DETECTORS.

TO WIT: HARDWIRED SMOKE DETECTORS ARE NOT BEING MAINTAINED IN ACCORDANCE WITH NFPA 101:31.3.4.5.1.

CORRECTIVE ACTION: INSTALL HARDWIRED SMOKE DETECTORS IN ACCORDANCE WITH NFPA 101:31.3.4.5.1. POWERED BY THE BUILDINGS ELECTRIC SYSTEM WITH BATTERY BACK?UP

- 7. NFPA 101:7.2.1.8.1 REPAIR ALL DOORS TO SELF? CLOSE AND LATCH.
- TO WIT: SELF CLOSING OR AUTOMATIC CLOSING DOOR(S) DON'T SELF CLOSE AND LATCH.

CORRECTIVE ACTION: REPAIR THE SELF?CLOSING OR AUTOMATIC?CLOSING DOOR(S) TO SELF?CLOSE AND LATCH.

- 8. NFPA 101:7.2.1.8.1 REPAIR ALL FIRE RATED STAIRWELL DOORS.
- TO WIT: SELF CLOSING OR AUTOMATIC CLOSING DOOR(S) DON'T SELF CLOSE AND LATCH.

CORRECTIVE ACTION: REPAIR THE SELF CLOSING OR AUTOMATIC CLOSING DOOR(S) TO SELF CLOSE AND LATCH.

9. NFPA 1:11.1.2 REPAIR ALL EXPOSED WIRING. TO WIT: ELECTRICAL WIRING NOT PER NFPA 70, NATIONAL ELECTRICAL CODE.

CORRECTIVE ACTION: REPAIR ALL EXPOSED WIRING IN ALL APARTMENTS AND ON THE EXTERIOR OF THE STRUCTURE.

REPAIR WIRING TO BE CONSISTENT WITH NFPA 70, NATIONAL ELECTRICAL CODE.

10. NFPA 1:4.5.8.6 REPLACE / REPAIR ALL MISSING HAND RAILINGS.

TO WIT: SAFEGUARDS, RAILING ARE MISSING AND HAVE BEEN REMOVED FROM THE 4TH FLOOR AND ARE NOT SECURED IN AREAS OF THE 3RD AND 2ND FLOOR. CORRECTIVE ACTION: PERMITS SHALL BE OBTAINED TO SECURE AND INSTALL THE PROPER FALL PROTECTION.

11. 9999 UNSAFE BUILDING.

TO WIT: THE BUILDING OFFICIAL OF THE CITY OF FORT LAUDERDALE HAS POSTED THIS PROPERTY AS AN UNSAFE STRUCTURE TODAY (TUESDAY AUGUST 4th, 2015). CORRECTIVE ACTION: COMPLY WITH THE ORDER OF THE BUILDING OFFICIAL.

12. NFPA 1:11.1.10 REPLACE ALL MISSING ELECTRICAL COVERS.

TO WIT: THERE IS/ARE MISSING ELECTRICAL COVER(S). CORRECTIVE ACTION: REPLACE ALL MISSING ELECTRICAL COVERS IN ALL APARTMENTS AND ELECTRICAL PANELS. REPLACE ALL MISSING ELECTRICAL COVERS.

FBC(2014) 116.2.1.2.1

- 1. THERE ARE BALCONY RAILINGS WHICH HAVE BROKEN FREE AND ARE NOW ATTACHED WITH ANGLE BRACKETS. THESE RAILINGS ARE LOOSE AND CAN EASILY BE BROKEN FREE CAUSING A FALL HAZARD AND IS A LIFE SAFETY ISSUE.
- 2. THERE ARE OVERHEAD LIGHT FIXTURES THAT HAVE BROKEN FREE AND ARE HANGING LOOSE AND ARE A POTENTIAL LIFE SAFETY ISSUE.

FBC(2014) 116.2.1.2.2

1. THERE ARE SEVERAL AREAS THROUGHOUT THE BUILDING WHERE THERE IS SIGNIFICATE DETERIORATION OF THE CONCRETE COLUMNS, CONCRETE BEAMS, AND CONCRETE WALKWAYS WHERE REBAR IS EXPOSED. THIS DETERIORATION HAS COMPROMISED THE STRUCTURAL INTEGRITY OF THIS BUILDING CAUSING POTENTIAL LIFE SAFETY ISSUES.

FBC(2014) 116.2.1.3.1

- 1. THERE IS AN ILLEGAL GAS LINE INSTALLED ON THE NORTH SIDE OF THE BUILDING. THIS ILLEGAL GAS LINE WAS INSTALLED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS. THE GAS LINE IS BLOCKING TWO DOORS MAKING THEM UNABLE TO BE OPENED.
- 2. THERE ARE MULTIPLE UNITS THAT ARE IN THE

PROCESS OF BEING REMODELED. THIS WORK INCLUDES BUT IS NOT LIMITED TO THE DEMOLITION OF KITCHENS AND BATHROOMS, PLUMBING, ELECTRICAL AND STRUCTURAL WORK BEING DONE. THIS WORK HAS COMMENCED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

CASE NO: CE15030470
CASE ADDR: 201 NE 16 AV
OWNER: HINDS, KEVIN &

LAYNE, PAUL J
INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS PROPERTY HAS BEEN ALTERED WITH STRUCTURAL ALTERATIONS DONE WITHOUT THE REQUIRED STRUCTURAL PERMIT AND/OR INSPECTIONS. THIS WORK INCLUDES BUT

IS NOT LIMITED TO:

- 1. SECOND BATHROOM INSTALLED.
- 2. ROOMS SUB-DIVIDED WITH INTERIOR WALLS TO CREATE NEW ROOMS.
- 3. WOOD DECK WITH A WOOD PRIVACY SCREEN.

FBC(2010) 105.4.15

THIS PROPERTY HAS BEEN ALTERED WITH THE INSTALLATION OF NEW WINDOW AND DOORS WITHOUT THE REQUIRED PERMITS AND OR INSPECTIONS.

FBC (2010) 105.4.4

THIS PROPERTY HAS BEEN ALTERED WITH THE INSTALLATION OF PLUMBING WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS WHICH INCLUDES BUT IS NOT LIMITED TO:

1. A SECOND BATHROOM INSTALLED WITH A SHOWER, TOILET AND SINK.

FBC(2010) 105.4.5

THIS PROPERTY HAS BEEN ALTERED WITH THE INSTALLATION OF ELECTRICAL WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS THAT INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL INSTALLED IN THE SECOND BATHROOM AND OTHER CREATED ROOMS.

FBC(2010) 110.9

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE AFTER THE FACT PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY UNDER F.B.C. 109.3.3

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15091319
CASE ADDR: 307 NE 23 AV

OWNER: WALTER A CROWELL TR

CROWELL, WALTER A TRSTEE

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO:

1. THE INSTALLATION OF AN OUTDOOR KITCHEN

STRUCTURE BUILT WITHOUT THE REQUIRED PERMIT AND/OR

INSPECTIONS.

FBC (2014) 105.3.1.4.4

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO:

1. THE INSTALLATION OF A GAS LINE INSTALLED FOR AN OUTDOOR KITCHEN WITHOUT THE REQUIRED PERMITS

AND/OR INSPECTIONS.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE

IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15091850

CASE ADDR: 200 S BIRCH RD # 1011
OWNER: FRENI MEHTA REV TR

MEHTA, FRENI TRSTEE

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC (2014) 105.1

THIS CONDO UNIT HAS BEEN ALTERED WITH A COMPLETE RENOVATION WHICH INCLUDES BUT IS NOT LIMITED TO:

- 1. WINDOWS AND DOORS BEING REPLACED.
- 2. FULL KITCHEN REMODEL TO INCLUDE THE FRAMING DOWN OF THE KITCHEN CEILING AND INSTALLING DRYWALL.
- 3. FULL BATHROOM RENOVATION WITH INSTALLATION OF DRYWALL/TILE BACKING BOARD.

THIS WORK HAS BEEN PERFORMED WITHOUT THE REQUIRED STRUCTURAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS CONDO UNIT HAS BEEN ALTERED WITH THE INSTALLATION AND ALTERATIONS OF THE PLUMBING SYSTEM WHICH INCLUDE BUT IS NOT LIMITED TO:

- 1. INSTALLED A TANKLESS WATER HEATER.
- 2. CONVERTED THE TUB INTO A SHOWER.
- 3. REPLACED THE SHOWER VALVE.
- 4. REMOVED AND REPLACED ALL THE PLUMBING FIXTURES IN BOTH THE KITCHEN AND BATHROOM WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS CONDO UNIT HAS BEEN ALTERED WITH THE INSTALLATION AND ALTERATIONS OF THE ELECTRICAL SYSTEM WHICH INCLUDES BUT IS NOT LIMITED TO:

1. WIRING, OUTLETS, SWITCHES, DEVICES AND THE WIRING OF A TANKLESS WATER HEATER.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THIS CONDO UNIT AND THE CONDO BUILDING, PROFESSIONAL DRAWINGS PREPARED BY A DESIGN PROFESSIONAL WILL BE REQUIRED TO ADDRESS EACH VIOLATIONS AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

FBC(2014) 109.3.3

THE CONDO UNIT OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES OR POSSIBLY QUADRUPLE FEES THAT WILL BE APPLY.

FBC(2014) 110.6

SCHEDULED AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED.

CASE NO: CE14120581 CASE ADDR: 3001 SE 5 ST

OWNER: SOPHIA ENTERPRISES INC

INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC(2010) 105.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. NEW PLUMBING FIXTURES IN SECOND FLOOR RESTROOMS.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE15050511 CASE ADDR: 1132 NW 5 CT

OWNER: MCCULLOUGH, JOHNNY

HALL, ODESSA

INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED

PERMITS AND INSPECTIONS.

1. THIS SINGLE STORY DUPLEX HAS BEEN CONVERTED

INTO A FOURPLEX.

FBC (2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITING PROCESS.

FBC(2010) 111.1.1

THE USE AND THE OCCUPANCY OF THIS DWELLING HAS

BEEN CHANGED FROM THE ORIGINALLY PERMITTED

OCCUPANCY CLASSIFICATION OF A DUPLEX TO A FOURPLEX

WITHOUT OBTAINING THE REQUIRED PERMITS AND THE

CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT.

CASE NO: CE15070227
CASE ADDR: 1032 NE 8 AV
OWNER: ACOMB, JACK

ACOMB, LAWRENCE T

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. WOOD FENCE WITH NO PERMIT.

2. CONSTRUCTION OF AN ENCLOSURE WITH NO PERMIT.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITING PROCESS.

CASE NO: CE15070786
CASE ADDR: 1437 NE 56 ST
OWNER: BRODETZKI, YUVAL

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THE BUILDING HAS BEEN ALTERED WITHOUT A PERMIT. IT HAS BEEN CONVERTED TO FIVE UNITS. APPROVED USE IS

FOR A SINGLE UNIT FAMILY RESIDENCE.

FBC(2014) 105.4.1.2

OWNER OF RECORD IS RESPONSIBLE TO ABIDE BY FLORIDA BUILDING CODE AS OUTLINED IN FLORIDA STATUTES.

FBC(2014) 105.3.1.4.4

THE PLUMBING HAS BEEN ALTERED WITHOUT A PERMIT.

FBC(2014) 105.3.1.4.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED WITHOUT A PERMIT.

FBC(2014) 105.3.1.4.11

THE MECHANICAL SYSTEM HAS BEEN ALTERED WITHOUT A PERMIT.

FBC(2014) 105.3.1.4.15

WINDOW AND DOOR INSTALLATIONS AND ALTERATIONS WITHOUT A PERMIT.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITING PROCESS.

FBC(2014) 111.4.1

PROPERTY IS A SINGLE FAMILY RESIDENCE APPROVED FOR SINGLE USE. THE USE AND THE OCCUPANCY OF THIS DWELLING HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION OF A SINGLE FAMILY TO A FIVEPLEX WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT.

CASE NO: CE15072462
CASE ADDR: 1119 NE 15 AVE
OWNER: 1119 PROGRESSO LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. KITCHEN/BATH REMODEL WITHOUT PERMIT.
- 2. CONVERTED GARAGE INTO A BEDROOM AND/OR LIVING SPACE WITHOUT PERMIT.
- 3. REMOVED AND REPLACED FIXTURES.
- 4. ATF PERMITS THAT WERE APPLIED FOR WERE VOIDED AND/OR NOT ISSUED.

FBC (2014) 105.3.1.4.4

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF PLUMBING COMPONENTS AND/OR MODIFYING THE PLUMBING SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING PLUMBING COMPONENTS THAT MAY INCLUDE PLUMBING FIXTURES SUCH AS VALVES, TOILETS, SINKS, DIVERTERS, SHOWER HEADS, WATER SPIGOTS, WATER LINES, WASTE DISPOSAL PIPES, WATER HEATERS, IRRIGATION SYSTEM, PUMPS AND OTHER PLUMBING COMPONENTS CONNECTED THE PLUMBING SYSTEM.

FBC(2014) 105.3.1.4.5

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF ELECTRICAL COMPONENTS AND/OR MODIFYING THE ELECTRICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING ELECTRICAL COMPONENTS THAT MAY INCLUDE SWITCHES, OUTLETS, ELECTRICAL FIXTURES, BREAKER/PANEL BOXES, METER BASES, WIRES, REWIRING AND OTHER ELECTRICAL COMPONENTS CONNECTED TO THE ELECTRICAL SYSTEM.

FBC(2014) 105.3.1.4.11

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF THE MECHANICAL COMPONENTS AND/OR MODIFYING THE MECHANICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING CONDENSER UNITS, EVAPORATOR UNITS, DUCT WORK, ELECTRICAL COMPONENTS, THERMOSTATS, COOLING TOWERS, HEATERS, AND OTHER MECHANICAL COMPONENTS CONNECTED TO THE MECHANICAL SYSTEM.

FBC (2014) 110.2

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITING PROCESS.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITING PROCESS.

CASE NO: CE15080572 CASE ADDR: 1201 NE 5 AV

OWNER: EM INVESTMENT REV TR

MILITZOK & LEVY PA

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. ADDED A FIFTH UNIT TO A FOURPLEX, ALTERED THE CONFIGURATION OF THE WALLS, THE ELECTRICAL, MECHANICAL AND PLUMBING.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITING PROCESS.

FBC(2014) 111.1.1

THE USE AND THE OCCUPANCY OF THIS DWELLING HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION OF A FOUR UNITS TO FIVE UNITS WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT.

FBC(2014) 111.4.1

UNIT OCCUPIED IN VIOLATION OF THIS CODE MUST BE VACATED.

CASE NO: CE15092059
CASE ADDR: 1544 NW 9 AVE
OWNER: KDE OF FL 1 LLC

INSPECTOR: JOSE ABIN

FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. REMODELING AND ALTERATIONS TO THE STRUCTURE. WINDOWS, DOORS, WALLS, BATHROOMS REMODEL, KITCHEN REMODEL, PLUMBING.

FBC(2014) 105.3.1.4.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. STRUCTURAL MODIFICATIONS OF INTERIOR WALLS.

FBC(2014) 105.3.1.4.4

ALTERING, REPAIRING, INSTALLATION OF PLUMBING COMPONENTS AND/OR MODIFYING THE PLUMBING SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS. INSTALLATION AND MODIFICATION BUT NOT LIMITED TO:

1. BATHROOM REMODEL WITH PLUMBING ALTERATIONS.

FBC(2014) 105.3.1.5

WHERE APPLICABLE PERMIT REQUIREMENTS MUST HAVE SUPPORTING DOCUMENTATION FROM A QUALIFIED DESIGN PROFESSIONAL.

FBC(2014) 105.4.1.2 OWNER RESPONSIBILITY.

FBC(2014) 105.3.1.4.15

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLATION OF DOORS AND WINDOWS.

FBC(2014) 105.19.2

THE BUILDING OFFICIAL AT HIS/HER DISCRETION SHALL INTERPRET THE BUILDING CODE AND COMPLIANCE REQUIREMENTS.

FBC(2010) 111.1.1

THE USE AND THE OCCUPANCY OF THIS DWELLING HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION OF A SINGLE FAMILY HOME TO A DUPLEX WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT.

FBC(2014) 109.3.3

THIS CODE CASE WILL REQUIRE ALL PERMITS TO BE DOUBLE FEE.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

FBC(2014) 115.1

STOP WORK ORDER ISSUED SINCE WORK IS ONGOING WITHOUT THE REQUIRED PERMITS.

FBC(2014) 116.1.2

THIS BUILDING IN ITS PRESENT CONDITION DOES NOT MEET THE CRITERIA OF THE FLORIDA BUILDING CODE FOR MINIMUM MAINTENANCE STANDARD AND THE FORT LAUDERDALE MINIMUM HOUSING CODE AND IT MUST BE REPAIRED BY THE OWNERS OR DEMOLISHED:

1. PER FLORIDA BUILDING CODE WORK WITHOUT PERMIT IS DEEMED TO BE UNSAFE.

CASE NO: CE15121199

CASE ADDR: 1251 E SUNRISE BLVD
OWNER: ROSHNI INVESTMENTS INC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 1013.4

1. OPENING ON GUARDRAILS EXCEED THE MAXIMUM ALLOWABLE UNDER THE SECTIONS OF THIS CODE OF 4 INCHES.

2. THIS IS AN EXIGENT LIFE AND SAFETY HAZARD THAT IMMEDIATE ATTENTION IS REQUIRED TO MAKE SAFE.

FBC(2014) 110.6

THIS VIOLATION IS IN PROGRESS AND REQUIRES INSPECTIONS AND APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE MITIGATION AND PERMITTING PROCESS.
